

# F00RJ01714 Injector Valve Assembly Technical File



Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

Website: www.shumatt.com

# F00RJ01714 Injector Valve Assembly Technical File

## Content

والمالية 2.F0(	. F00RJ01714 Injector Valve Assembly's Introduction											
3.F00	ORJ01714	Valve Ass	embly's P	urchase	and Deli	very		200 P. J. Co.	300	St. State	-30 Sec.	. 10
	3.1.F00RJ	01714 Va	lve Asser	nbly Pur	chase Pa	ayment T	erms					. 10
67	3.2.F00RJ	01714 Val 01714 Val	lve assem	nbly's Ma	in Sales	Market	i	i	i	î <u></u>	î <u></u>	. 10
ST.	3.3.F00RJ	01714 Val	lve assem	ibly's Dec	claration	ı Require	ements					. 10
	3.4.F00RJ	01714 Val 01714 Val	lve Assen	าbly's Shi	pping W	ays						10
-2137	3.5.FUUKJ	01714 Val	ive Assen	ibly's Lea	ad lime.							10
01	3.6.FUUKJ 2 7 EAADI	01714 Val	ive Assen	ndiy S Lo	gistics II	ime for D	estinatio	on Out of	Gnina s	Areas		<b>I</b> U 11
4 E00	3.7 <u>.</u> 1.00KJ NRIN1 <i>7</i> 1 <i>4</i>	01714 Val Valve Asso ormation.	ombly's S	torage St	tandard	7. 1985.	7 7	1	T	7 1700 m	9 12000	12
5 Co	mnany Inf	ormation	cilibly 3 3	itorage 3	tanuaru.	- State	SP	SHOP	80000	- 500 mm	37	12 13
J. CO	5.1 Comr	any Intro	duction		••••••	•••••	• • • • • • • • • • • • • • • • • • • •	••••••	•••••	•••••	•••••	<u>1</u> 3
. 100	5.2. Sales-	men's Con	itact Info	rmation	1	S. 100	V	·	17000	7 1800 - 1		13
6 Cc	3. <u>2</u> . 3dic3	men o con	icact iiiioi	i i i i a ci o i i								
U. C	povright St	atement	300m	-600,000	dillo.	400	Ship.	Supple	3200	33,000	90 <sup>0</sup>	13 14
0. CC	opyright St	atement	9000	-97%	900	4000	91 <sup>(2)</sup>	93 <sup>1</sup>	3700	30000		14
0. در	opyright St	atement	2000 2000 2000	SHE.	A STAN	e de la company de la comp Company de la company de la co		37 <sup>1</sup>	\$ 1900 T	SHOW.	5180m	14
91 <sup>6,300</sup>	opyright St	atement	214900941 1	ZIJETUSEL.	ati <sub>ghtea</sub> t i	e de partie e de la composition della compositio	SUPPLIED.	244 <sub>786</sub> 2, ,	Shranger.	aliferative,	Shipping,	. 14
STAIR	opyright St	atement	Shrapat,	Electron.	SHEARN.	Shranki i Shranki	STANSON S	STANDAL STANDAL STANDAL		SHARAK SHARAK	Shows	14
SPANI SPANI		LL SHERML	SHOWL SHOWL SHOWL	SHEDEN.	SPERMIT	SPANNEY SPANNEY	SPANNE	SPATERY.	Shrank.	SATAN.	SHOWL SHOWL SHOWL	
		TT SHOWN	SHARK SHARK	SHOUTH TO	SPECIFIC SPECIFIC	SPLEET,	SPANNET SPANNET SPANNET SPANNET	SPANNET SPANNET SPANNET	SHOOM,	SPANNE SPANNE SPANNE	SPACES TO	
		TT SHEARNT	SPLEETE, SPLEETE, SPLEETE, SPLEETE,	SPLOTERY	SPLEET SPLEET	SPLEET, SPLEET,	SPANNET SPANNET SPANNET SPANNET	SPANNET SPANNET SPANNET	SHARK!	SHADN'S SHADN'S SHADN'S	SPROMET SPROMET SPROMET	
		TT SHADONT	SPLOWE SP	SPECIAL SPECIA	SPLEET SPLEET	SPLEET, SPLEET, SPLEET,	SPANNET SPANNET SPANNET SPANNET	SPARSE SPARSE	SHARK!	SPACE TO SPACE THE SPACE T	SPACE TO SPACE TO SPACE TO SPACE TO STATE TO SPACE TO STATE TO SPACE TO SPA	
		TT SHADONT	SPLEETER SPL	SPECIAL SPECIA	SPLEETERS SPLEET	SPARSET SPARSET	SPANNY SPANNY SPANNY	SPACE TO SPA	SHARKS.	SPACE TO SPA	SPLOWER SPLOWE	

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com Website: www.shumatt.com



## F00RJ01714 Injector Valve Assembly Technical File

## 1. F00RJ01714 Injector Valve Assembly's Introduction

1.1.F00RJ01714 Injector Valve Assembly's Basic Information

Title	China made brand new fuel injector valve assembly F00RJ01714
SKU1	G1S8F00RJ01714
SKU2	G1L10F00RJ01714/G1L10F00RJ01714
SKU3	G1N3F00RJ01714/N30000B2BJ01714

# 1.2.F00RJ01714 Injector Valve Assembly's Application Information for Injectors


(1) F00RJ01714 Injector Valve Assembly's Car Model Matching Information

Injector Part Number	Car Model	OE Number	OE Number	OE Number	OE Number	OE Number	OE Number
100111001				3 970	,	1101111001	
0 445 120 050	CUMMINS	3 999 834	3 999 832	985	i i i i i i	-00 <sup>1</sup>	ęt.
31 <sup>1</sup>	3/1/200	Same of the same	francista St	3 970	31 31 SI	377	378
0 445 120 071	CUMMINS	3 999 832	4 940 096	987			
and the second	CUMMINS	4 988 835	aller and the same		Salation of the salation of th	gather a gath	5.5 88
	FORD	BH1X 9K526 CA					- S
Strang. St.	TATA (TELCO)	570107999909	State State St	And State of the S	sit <sup>utati</sup> sit	1000 - 1000 C	98 <sup>3</sup>
0 445 120 161	TEMSA	4 988 835		_			-
0 445 120 177	CUMMINS	5 254 261		State of the state	and State of the	gir Company	17 2018
0 445 120 184	CUMMINS	4 981 077	o der der	541	51	57	
0 445 120 185	CUMMINS	4 981 076	and the same of the same of	Prince Prince	i marii	777 m	Ø J
8844, 884	CUMMINS	4 983 514	5 256 034	\$177	21m, 21	2000	4000
-197 <sup>ct</sup>	DODGE	68210 512AA	Mrs. Mrs.	Jan Par	i Day	Jan 19	ÇÎ.
0 445 120 187	RAM	68210512AA	tim stim st	S/1500	aliman ali	200	327
-4	CUMMINS	4 994 928	- T		9		e-0
SHADON SH	DODGE	68086 182AA		200g, "P100g,,			330
0 445 120 188	RAM	68086182AA					
100 Miles	CUMMINS	5 253 220	5253220-NX		The second second	5011 <sup>55</sup> 25501	(1) (1)
-977 -977	24. 3	200 3	r. 3r. 3r.	68002	R8069384	68027	68027
-1875.	DODGE	68002 012AA	68069 384AA	012AB	AA	067AA	.067AB
0 445 120 193	RAM	6806 9384AA	6800 2012AA	6800 2012AB	R8069384 AA	377	81 <sup>8</sup>
- 100 Care	CUMMINS	5 253 221	The The	Steen Plans	1 200	est in	ď.
50 <sup>6</sup> 0000 50 <sup>6</sup>	38,000	900	the still still	09864	30,000	50/2	300
0 445 120 204	DODGE	9864 35519	68002 012AC	35519		and a	er(
ale de la companya de	CUMMINS	5 269 194	all the sales		at a state of	griff. " all drift.	48
0 445 120 267	HINO	89550E0072		-			m <sup>2</sup>
0 445 120 269	HVECO - marini	8052934	Then Then.	marin marin	1	House Philosophia	67

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com Website: www.shumatt.com



0 445 120 332	CUMMINS	5 262 128					
0 445 120 384	CUMMINS	5 310 954	Mary Mary	Allera Marie	100	est <sup>riff</sup> Lest	gi j
0 445 120 336	CUMMINS	5 289 380	en Ston St	36		5%	577
_80	CUMMINS	4 994 925	in in	et - et	i edi		eS.
State of	DODGE	68210105-AA	Arrest States St		sh <sup>gov</sup> - sh	an Alban.	98 <sup>80</sup>
0 445 120 342	RAM	68210105AA	4 994 925				-t
0 445 120 356	CUMMINS	5 303 101			all <sup>flift</sup> all	Marin State Contraction	10 2010



© 2022 Shenzhen Shumatt Technology Co., Ltd

Email: <u>ruby@shumatt.com</u> Website: <u>www.shumatt.com</u>



(2) F00RJ01714 Injector Valve Assembly's Application for Injectors' Part Number

Injector Series	Injector Part Number	System Pressure	Re-manufactured Part Number	System Pressure	Universal Number	System Pressure	Universal Number	System Pressure
CRIN3-18	0 445 120 050	C. Christian Christ	0 986 435 518	1800	0 445 120 185	SARAL SARAL	0 445 120	1800
CRIN3-18	0 445 120 071	KT JAKOSHTT JAKOS	0 986 435 519	1800	0 445 120 204	1800	( 	
CRIN3-18	0 445 120 161	1800	0 986 435 645	71 21	301	21 - 21	-	
CRIN3-18	0 445 120 177	1800	May Strike Strike Strike	Sign Signature, 21	One Phone Control	Strange, Strange,	51 <sup>85</sup>	
CRIN3-18	0 445 120 184	T STATE STA	0 986 435 519	1800	0 445 120 204	1800	e de la companya de l	
CRIN3-18	0 445 120 185	T AND TO AND	0 986 435 518	1800	0 445 120 193	1800	(	
CRIN3-18	0 445 120 187	1,800	0 986 435 573	1800	F 00E 200 419	**************************************	84.	
CRIN3-18	0 445 120 188	1800	0 986 435 574	1800	F 00E 200 420	28/4 23/4	i Shp	
CRIN3-18	0 445 120 193	1800	0 986 435 518	1800	37,500	Strange Strange	44	
CRIN3-18	0 445 120 204	1800	0 986 435 519	1800	The Property	Transport Transport	í	
CRIN3-18	0 445 120 267	1800	St. Ste. St.	\$17 \$1	3,00	24	31,	
CRIN3-18	0 445 120 269	1800	ATT CARREST CARREST CAR	OFFICE STREET	UNITE LUNGTY	-3.50 MT -3.50 MT		
CRIN3-18	0 445 120 332	1800		301 301	380	P1 - 301	-	
CRIN3-18	0 445 120 336	1800	W. Christian Strain, Stor	alenge al		SAME SAME	sk <sup>g</sup>	
CRIN3-18	0 445 120 342	1800	0 986 435 621	1800	ati ati	.d .d		

Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

Website: www.shumatt.com

SHUMATT

Shenzhen Shumatt Technology Co., Ltd

CRIN3-18	0 445 120 356	1800	775. 775. 775	ari ari	.et .et	75. The	Ç	
CRIN3-18	0 445 120 384	1800	0 986 435 644	34 <sub>700</sub> , 34	200 - April .	ghilling ghilling	Sty.	

Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

SHIME © 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

Website : <u>www.shumatt.com</u>

## (3) F00RJ01714 Injector Assembly Part Number Common Writing

FOORJO1714, FOORJO

#### 1.3.F00RJ01714 Injector Valve Assembly's Specifications and Dimensions Parameters

Valve Assembly Size: 13 cm\*2 cm \*2 cm
Valve Assembly Box Size: 14 cm \*3 cm \*3 cm
Valve Assembly Packing Size: 31 cm \*12 cm

Valve Assembly Net Weight: 0.03kg
Valve Assembly Gross Weight: 0.03kg

Valve Assembly Quality: China Made Brand New Injector Valve Assembly

Valve Assembly MOQ: 4 PCS

## 1.4.F00RJ01714 Injector Valve Assembly's Quality Control

## (1) Valve Assembly Testing

All parts of the injector valve assembly are subjected to precision testing, high temperature testing, low temperature testing, withstand pressure testing, leakage testing, durability testing, and various working conditions testing.

## (2) Injector Valve Assembly Inspection

The factory inspection of the injector valve assembly is undergone full inspection, random inspection, and batch inspection three inspections. Different brands of test benches are used to test the same injector valve assembly for a total of no less than three times for factory inspection, and the fuel injector installation testing environment are progressed in dust-free workshop.

## (3) Injector Valve Assembly Installation

When matching the valve cap and valve steam, Shumatt strictly complies with the standard of valve cap and valve stem clearance technical indicators to ensure that each valve assembly meets the factory standards and use standards.

#### 1.5.F00RJ01714 Injector Valve Assembly's Customized Service

(1) Valve Assembly's Customized Service: Meet the customized needs of OEM manufacturers for shell lettering, logo engraving, injector internal packaging, injector external packaging and labels customized, etc.

icttering, logo engraving, injector inte	mai packaging, injector external packaging and labels customized, etc.
9 9	
•	
3 3	
AWE AWE AWY AWY	
Valva Can Color Customized 1000	Valve Cap Color Customized 1000
Valve Cap Color Customized 1000	pieces (Purple and red color are Valve Cap Groove Customized
pieces (White color is optional)	optional)
977	
an al	STATE OF THE STATE
1	AND THE STREET
Valve Cap Lettering Valve Cap logo	
Engraving Valve Cap QR Code Engraving	Valve Assembly Box (Square is optional)  Valve Assembly Box (Cylindrical is optional)

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: <u>ruby@shumatt.com</u> Website: <u>www.shumatt.com</u>





## (2) Valve Assembly's Customized Service Requirements:

Customized valve assembly box are no less than 100 pieces.

Customized valve assembly groove no less than 100 pieces.

The purchased of customized valve assembly are no less than 1000 pieces.

The purchased of customized valve cap engraving contents are no less than 1000 pieces.

The purchased of customized valve colors are no less than between 1000 -10000 pieces.

Customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file.

▲ Once the customized injector valve assembly is sold, it can not be returned or exchanged if there is no quality problems.

#### 1.6.F00RJ01714 Injector Valve Assembly's Packing List

(1) Valve Assembly's spare parts list

Serial Number	1	2	3
SAN SAN SAN	Shumet State	516.35% S16.35%	en, en, en,
STATE STATE	68° 85°	all our our off	
Name	Injector Valve Assembly	Valve Assembly Anti-rust Paper	Valve Assembly Box(Square is optional)
Description	Valve Assembly Part Number F00RJ01714	Prevent the valve assembly from rusting	Protect the valve assembly from being damaged by colliding
Serial Number	4	2 344. 344.	844., 844., 844., 844.
Image			
Name	Valve Assembly Box (Cylindrical is optional)	VCI Anti-rust Bag	ATT WASTER WASTER WASTER
Description	Protect the valve assembly from being damaged by colliding	Prevent the valve assembly from rusting	

- ▲ Minors are prohibited from using the injector valve assembly, valve assembly anti-rust paper, valve assembly box, and VCI anti-rust bag to avoid personal injury.
- ▲ The valve assembly box is recyclable and can be reused.
  - ▲ VCI anti-rust bag is non-degradable material, please dispose of it properly after use.

## 1.7.F00RJ01714 Injector Valve Assembly's Warranty Instructions

## (1) . Valve Assembly Warranty Conditions and Instructions

It is necessary to provide pictures, videos, or test reports detected by the injector valve assembly inspection equipment when the valve assembly is abnormal during use as evidence to feed back to the

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com

salesman.

Abnormal conditions are properly explained such as: 1. Smoke, 2. Engine shake, 3. Difficulty starting SHIPPE the engine, 4. Engine noise, 5. oil leakage etc.

## (2) . Valve Assembly Warranty Coverage

Within 15 days after customer receives the F00RJ01714 injector valve assembly, if there is a performance failure and the product has no appearance damage, customer can choose to replace it or The The Time The The The The The The The

200

If the F00RJ01714 injector valve assembly has performance problems during the warranty period (3 months), and it is confirmed that it is product's problems after testing, you can contact our salesmen to replace the same model or a reworked product with the same performance for free;

If the injector house has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free. 17)78(E)

# (3) . Injector Valve Assembly Out of Warranty Coverage The warranty period has expired.

THERE THERE

The warranty period has expired.

Injector valve assembly failure caused by high temperature, high pressure, humidity, rain and snow, saline-alkali land, earthquake, and used in abnormal environment.

Injector valve assembly damage caused by man-made reasons (throwing, strong magnetic field JUD 1997 July 1997 magnetization, set fire). 35 THE STATE OF TH 35999

Injector valve assembly failure or injector damage caused by non-injector design, technology, manufacturing, quality and other issues.

Injector valve assembly failure due to system pressure exceeding system approved pressure.

Injector valve assembly failure caused by system voltage exceeding approved voltage.

Injector valve assembly failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.

Injector valve assembly failure caused by not installing according to the tightening torque specified in the vehicle engine maintenance manual (the tightening torque is too large or too small).

Injector valve assembly failure caused by not following the installation angle specified in the injector maintenance manual.

Injector valve assembly failure caused by not following the cleaning requirements specified in the injector maintenance manual.

Injector valve assembly failure caused by failure to replace consumable parts as specified in the injector maintenance manual.

## 1.8.F00RJ01714 Injector Valve Assembly's Manufacturer

Injector Valve Assembly's Manufacturer: Shenzhen Shumatt Technology Co.,Ltd

## 2.F00RJ01714 Injector Valve Assembly Technical Support


## 2.1.F00RJ01714 Injector Valve Assembly's Installation Precautions

- to make the stains, dust, rust-proof oil oxides, paraffin base, naphthenic base, intermediate base, salt, lead naphthenate, zinc naphthenate sodium naturals. Clean the injector valve assembly in an ultrasonic cleaner for 3-5 minutes before installation, so as sulfonate, calcium petroleum sulfonate, tallow diamine trioleate, rosin amine on the surface of the valve assembly fall off. 25 400 200
  - Use compressed air to clean the cleaning fluid attached to the surface of the valve assembly after cleaning, and clean it up to the standard of use, as below


Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com





(3) When installing the valve stem, make sure that the valve stem and the bonnet must ensure that the valve stem can move smoothly in it. as below



If the injector steel ball and the ball seat are not installed in accordance with the standard, it may cause serious damage to the injector valve assembly

## 2.2.F00RJ01714 Injector Valve Assembly Replacement Conditions

#### (1) Valve Cap

Under the microscope, magnify 20 times to check that the oil inlet hole of the valve cap and the oil return hole of the bonnet are not worn, grooved, scratched, damaged, rusted or dented.



▲ The wear of the top oil return hole causes the oil return to be too large and the leaking injector cannot inject oil

▲ The side inlet hole is blocked causing the injector to establish the pressure chamber and the injector to function normally

▲ Wear of the cap cavity can cause the injector to work properly when the injector is badly delayed.


Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



#### (2) Valve Rod

Microscope amplification 20 times, check the valve rod for wear, not smooth surface color, rust



▲ The excessive clearance between the stem wear and the housing and between the cap causes an injector delay

▲ The valve stem lag will cause the injector to start the solenoid to start, and the oil needle can not return quickly after the nozzle is opened

• Check the injector components before replacing the injector valve assembly according following the injector service manual to avoid further damage to the injector valve assembly.

#### 2.3.F00RJ01714 Valve assembly Technical Support Obtaining Methods

- (1) Valve assembly Technical file, visit <a href="http://shumatt.com">http://shumatt.com</a> to get the technical File
- (2) Injector Technical Videos

Facebook: Visit <a href="https://www.facebook.com/hison.li">https://www.facebook.com/hison.li</a> constantly follow can get more information.

**YouTube:** <a href="https://www.youtube.com/channel/UCByvYBx7VjV">https://www.youtube.com/channel/UCByvYBx7VjV</a> mAfxh Hu-aw to get the technical videos, constantly follow can get more information.

**Shumatt:** Visit <a href="http://shumatt.com">http://shumatt.com</a> to get the technical videos.

(3) Valve Assembly Information Query Software

TruckBook Parts EPC APP, Android/Apple App Store download and install, visit <a href="http://shumatt.com">http://shumatt.com</a> to get the download and installation tutorial

(4) Search The valve assembly test data through TruckBook Parts EPC APP.

## 3.F00RJ01714 Valve Assembly's Purchase and Delivery.

#### 3.1.F00RJ01714 Valve Assembly Purchase Payment Terms

**Payment Terms:** T/T, PayPal, Alipay, WeChat

Please **c**ontact our salesmen for specific payment information.

## 3.2.F00RJ01714 Valve assembly's Main Sales Market.

Valve assembly main sales markets: Asia, Europe, North America, South America, Africa etc.

## 3.3.F00RJ01714 Valve assembly's Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

### 3.4.F00RJ01714 Valve Assembly's Shipping Ways

**Destination in China** areas: SF Express, Debon Express, the corresponding logistics company can be provided according to customer requirements in special cases.

**Destination**s out of **China'**s areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers.

## 3.5.F00RJ01714 Valve Assembly's Lead Time

entron entron

**Lead time:** Send out within 3-7 working days after receiving payment (Except for special products and special cases).

## 3.6.F00RJ01714 Valve Assembly's Logistics Time for Destination Out of China's Areas

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



## **DHL Logistics Time:**

Country or Region of Departure	Hong Kong, China	Other Countries or Regions of Asia	Australia and New Zealand	Europe	America	Other Countries
China's Mainland	7 Days	7 Days	8 Days	8 Days	8-12 Days	7-10 Days

UPS Logistics Time: Country or Region of Departure: China's Mainland

Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time
Japan	3 Days	UK	5-7 Days	Egypt	5-7 Days
Turkey	5-7 Days	Singapore	3 Days	Switzerland	5-7 Days
Bahrain	5-7 Days	Latvia	7-10 Days	New Zealand	7-10 Days
Sri Lanka	5-7 Days	Thailand	3 Days	Austria	5-7 Days
Romania	5-7 Days	Vietnam	3-5 Days	Estonia	5-7 Days
Malaysia	3-5 Days	Israel	5-7 Days	Mexico	7-10 Days
France	5-7 Days	America	5-7 Days	United Arab Emirates	5-7 Days
Italy	5-7 Days	Netherlands	5-7 Days	Bengal	7-10 Days
Lebanon	5-7 Days	Philippine	3-5 Days	Greece	7-10 Days
South Korea	3 Days	Spain	5-7 Days	Myanmar	5-7 Days
Canada	5-7 Days	Germany	5-7 Days	Saudi Arabia	7-10 Days
Portugal	5-7 Days	Australia	5-7 Days	South Africa	7-10 Days
Denmark	5-7 Days	Belgium	5-7 Days	Ukraine	7-10 Days
India	7-10 Days	Qatar	7-10 Days	Poland	5-7 Days
Indonesia	3-5 Days	Morocco	7-10 Days	Pakistan	7-10 Days
Kuwait	7-10 Days	All Market Market			

The logistics time is for reference only, subjects are according to the actual arrival.

## 3.7.F00RJ01714 Valve Assembly's Packing

**Domestic express packaging:** Usually wrapped in waterproof scotch tape, such as picture No.2.

**International express packaging:** Wrapped with waterproof yellow tape After wrapping the black protective film, such as picture No. 3.

**Pallet Shipping:** Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 4, Also, the products can be packaged according to customers' requirements.

⚠ The packing tray is made of plastic and can be recycled.

Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are non-degradable materials, please dispose of them properly.

Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film, and white wrapping protective film to avoid personal injury.

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133
Email: ruby@shumatt.com Website: www.shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

11 / 14





Pic No.2 Domestic express packaging: Wrapped by Transparent tape



Pic No.3 International express packaging: Wrapped with yellow tape after wrapping black protective film



Pic No.4

Pallet Shipping: Use pallet that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties

#### 4.F00RJ01714 Valve Assembly's Storage Standard

#### (1) Choose a suitable storage place

The warehouse and cargo yard where the fuel injector is stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acid, alkali, salt and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry.

#### (2) Strict requirements of warehousing

Strict inspections should be carried out when the fuel injectors are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do anti-rust treatment in time. Packaged injectors must be protected from damage.

## (3) Keep the warehouse dry and preventing moisture

The relative humidity is usually below 70% for the fuel injectors placed in the room, and the corrosion of the fuel injectors is significantly reduced.

Injectors must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content. THE THE PERSON THE PERSON THE

## (4) Stack Properly

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Website: www.shumatt.com

Email: ruby@shumatt.com



After the injector is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the injector from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse

If the fuel injector package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

It is forbidden to leave the injector exposed in the air for a long time.

It is forbidden to store acid, alkali, salt and other substances together with the injector.

The unpacked fuel injector must be rust-proof during secondary storage.

#### 5. Company Information



## **5.1. Company Introduction**

Chinese Name: 深圳市舒马特科技有限公司

English Name: Shenzhen Shumatt Technology Co., Ltd

Mob Phone/WeChat: +86-13410541523

HK Telephone: +852-67653519
Telephone: +86-755-23215133
Email: ruby@shumatt.com
Website: www.shumatt.net

Shenzhen Office: 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway

Station, Bao'an District, Shenzhen, China's Mainland

**Shenzhen Office:** Room 428-430, Building B, Huafeng Zhigu Technology Industrial Park, Exit B, Fuyong Metro Station, Bao'an District, Shenzhen, China's Mainland

Hong Kong Office: Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

After-sales Service Address: Please contact our salesmen to obtain and provide the corresponding product maintenance reasons (Reference: 1.7, F00RJ01714 Injector Valve Assembly's Warranty Instructions)

#### 5.2. Sales-men's Contact Information

No. Name WeChat/ WhatsApp Email Facebook YouTube

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133
Email: ruby@shumatt.com Website: www.shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

13 / 14



1	Ruby	+86-13410541523	ruby@shumatt.com	Hison Li	Hison Li
2	lvy	+86-18025309821	sales@shumatt.com	Ivy Shumatt	Shumatt IVY
3	Rebecca	+86-18025349821	sales01@shumatt.com	Rebecca SHUMATT	SHUMATT Rebecca
4	Janny	+86-18028749821	sales02@shumatt.com	Janny shumatt	Janny Shumatt
5	Sam	+86-13316859821	Sales8@shumatt.com	Shumatt Sam	Sam Shumatt
6 , 5	Natalie Natalie	+86- 18938945856	sales15@shumatt.com	Shumatt Natalie	Lin Natalie
7	Ada	+86-1342286353	sales5@shumatt.com	Shumatt Ada	Ada Shumatt
8	Hison Li	+86-18318811871	web@shumatt.com	Hison Li	Hison Li
9	Mecca	+86-18938948618	sales11@shumatt.com	Shumatt Mecca	Shumatt Mecca
10	Eric A	+86 18319033618	sales3@shumatt.com	A 1900 A 1900	18 July 18 18 18 18 18 18 18 18 18 18 18 18 18
11	Wayne ( Joaquín en español )	+86-13316959821	wayne@shumatt.com	shumattwayne	Wayne Shumatt
12	Sylvia	+86 18312499884	sales6@shumatt.com	C. The second	all mall
831,714	377 ST. V	sit http://shumatt.com to	obtain the latest information of sale	s-men	21,22

PS: Shumatt's sales-men's emails are all end with @shumatt.com

## 6. Copyright Statement

The copyright of any contents "FOORJO1714 valve assembly technical file" (including but not limited to parameters, data, text, charts, images, sounds or videos, etc.) provided in "FOORJO1714 Valve assembly Technical File" belong to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify any contents in "FOORJO1714 Valve assembly Technical File" in any way. At the same time, any conditions to spread, re-post, display the contents of "FOORJO1714 Valve assembly Technical File" should indicate that the cited article is from Shenzhen Shumatt Technology Co., Ltd., Any actions failure to follow above conditions to use "FOORJO1714 Valve assembly Technical File" will violate the "Copyright Law of the People's Republic of China" and other laws and regulations and the provisions of relevant international conventions.



Mob/Whatsapp: +86 13410541523 Tel: +8675523215133
Email: ruby@shumatt.com Website: www.shumatt.com