

618C Series 9308-618C Injector Control Valve Technical File











618C Series 9308-618C Injector Control Valve Technical File Stranger, Stranger,

wat part and content of the

618	C Series 93	808-618C	Injector (Control Va	alve Tech	nnical File	e		On 1			3
1. 9	308-618C	Injector (Control Va	alve's Intr	oductio	n:	وريسالته		پيث <i>ت</i> و	çı:	وري	3
80/6	1.1.9308	-618C Inj	ector Cor	ntrol Valv	e's Basic	Informa	tion	Silling	Silvan	58,50	50 ^{35,500}	3
	1.2.9308	-618C Inj	ector Cor	trol Valv	e's Matc	hing Info	rmation.					3
, april 1	1.2.9308 1.3.9308	-618C Inj	ector Cor	trol Valv	e's Speci	fications	and Dim	ensions				4
.311.	1.4.9308	-618C Inj	ector Cor	ntrol Valv	e's Quali	ity Contro	ollo	,2311.	.3301.	380.	389.	4
	1.5.9308	-618C Inj	ector Cor	ntrol Valv	e's Custo	mized S	ervice	ويرسطته	وررسلتانه	ويرسسانه	ييرون المائت	4
St.	1.6.9308	-618C Inj	ector Cor	ntrol Valv	e's Packi	ng List	Sil.	2017200	550	525	52,300	7
	1 7 9308	-618C Ini	ector Cor	ntrol Valv	e's Warr	anty Inst	ructions					8
	1.8.9308	-618C Inj	ector Cor	trol Valv	e's Manı	ufacturer		of Charles	617°	⁽¹⁾		8
2.9	308-618C	Injector C	ontrol Va	lve Techr	nical Sup	port	301	360	350	389	3941	9
	2.1.9308	-618C Inj	ector Cor	trol Valv	e's Inspe	ction	gG	g:ii:	ورانتو	çi,5	ويلَبُهُ	9ت
$\mathcal{Q}_{k_1}^{(p)}$	2.2.9308	-618C Inj	ector Cor	ntrol Valv	e's Insta	llation	200000	100	2000		58 See	10
	2.3.9308	-618C Inj	ector Cor	ntrol Valv	e's Techi	nical Sup	port Obt	aining M	ethods			16
3.93	308-618C	Injector C	ontrol Va	lve's Pur	chase an	d Delive	ry					16
790	3.1.9308	-618C Inj	ector Cor	ntrol Valv	e's Purch	nase Payı	ment Ter	ms	.50.	250.	550.	17
	3.2.9308	-618C Inj	ector Cor	ntrol Valv	e's Main	Sales M	arkets	. I	gi	ç::	c5.5	17
50 ⁽⁶⁾	3.3.9308	-618C Inj	ector Cor	ntrol Valv	e's Decla	aration R	equireme	ents	20,4720.0	37,500	2000	17
												17
	3.4.9308 3.5.9308	-618C Inj	ector Cor	ntrol Valv	e's Lead	time	gr.			90° 	5 ⁽⁵⁾	17
84	25.0	-618C Inj	200	200	77.7	77.7	200	59.1	54.1	24.1	200	17
4.9	3.7.9308 308-618C	Injector C	ontrol Va	lve's Stor	age Star	ndard	981 ^{0,250}	531 ^{0,350}	5171,500	577,550	577,500	18
	ompany Inf 5.1. Comp	oany Intro	duction.		S	(1) (1)						19
30	5.2. Sales	-men's Co	ntact Inf	ormation	924	- Stat	901	30	30	357.	595."	20
6. C	opyright St			<u> </u>				::Ti	g1.1	gil		20
Style .	2400	2/2/200	31,300	\$15.00m	3/2/2000	24,000	25,000	24/200	25/2000	24,200	31,300	\$1 ²⁵
		J-C	-5	J-F	uel'	-3					0	-41
-084	entt	6 ¹⁷ 5/8,556	ALTERNATIVE	TT SPECTOR	Stands.	elenta)	er states	arti Salah	ri ^{ri} Sr ^{aj} ori	51 ⁵⁵ 51 ^{9,500}	SPEEDS	ette.
01		101		900	400	-0.5	911	- 31	01			
	entra establica	SPANN	TT SHEETH	SHEET S	ri Shiri	SHUM!	SHIPS	ST SHIP	SWIDT	SPACE	rit Spileni	gS.
21/17	28,000	23/2700	89,000	Shippon	25/2000	-24/2000	-24/200	24/200	24,000	25/2/2000	29,200	9/g
										2		
	pis ^{es}	80° 30° 50°	and supplied	SHEETH	T SPAN			5 ¹⁷⁵ _3556	SUNTH	SANA.	eri eri	20g (2.)
Jan.	,300.0	,80.,	39.	.804.	2987	51 ^{6,500}	SHIPS CL	eri Sh ^{ijbi}	,800.	.90.	.894.	298.1
	NECT.	STANO		SHAPERA.	Zhippy Li	Shipping	38/ ⁵⁸⁸	gr ^a SHAM	SINGE	STALLS	ett.	000
SH_{ij}	21/200	219,500	27/1/200	20 p. 2000	200	40000	370,000	SNATOR	S14-200	S18-200	S18-200	9/6
				. ed			-1					
	nis ^{ch} ni	p7 ⁽⁷⁾	No. Ph	7. P.	S. Jan	si ^{ri} s	97°	97 ⁴	80°	gC	ariioo	90°

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



618C Series 9308-618C Injector Control Valve Technical File

1. 9308-618C Injector Control Valve's Introduction

1.1.9308-618C Injector Control Valve's Basic Information

Title	China Made New 9308-618C Injector Control Valve				
SKU1	G1L109308618CD1				
SKU2	G1Z119308618CD1				

1.2.9308-618C Injector Control Valve's Matching Information

(1) Injector Control Valve's Application to Car Model

Injector Part Number	Car Model	OE Number	OE Number	OE Number
EJDR00001Z	C. Children, Shippen,	Physical Physical Res	THE SHIPPING SHIPPING	STATES OF
EJDR00002Z		4 4	-1 -1 -	
EJDR00301Z	FORD (TRUCK/I	1376694	3S7Q9K546AJ	The state of the state of
EJDR00401Z	FORD (TRUCK/I	2C1Q9K546AB	770 - 770 - 770a	The The I
EJDR00402Z	FORD (TRUCK/I	3S7Q9K546AB		stram stram st
EJDR00403Z	FORD (TRUCK/I	4C1Q9K546AB	AND MARKET SORT	1 - 00TT - 00TT .
EJDR00502Z	FORD (TRUCK/I	1307449	3S7Q9K546CB	sm sm sr
EJDR00601D	FORD (TRUCK/I	5S7Q9K546AB	AND THE WASHING	CONTRACT CARLEST CAR
EJBR00901Z	KIA	33800-4X500	10-1	
EJBR01001A	Shane, Shrane,	A STATE OF THE STA	Mary Mary Mary	Shippy Shippy Sh
EJBR01201Z	0 20 0	Set set	11 11 1	120 220 2
EJBR01302Z	47. July 19. 19. 19. 19. 19. 19. 19. 19. 19. 19.	Stephen Stephen Step	Ber alfager alfager	diplo. diplo. di
EJBR01401Z	Mary William D	Time Time	770 - 7780 - 7780	THE THE ?
EJBR01601Z	FORD (TRUCK/I	1S4Q9F593AF	a Ston Ston	24,000
EJBR01701Z	RENAULT	8200207935	DETT STEELS STEEL	THE THE S
EJBR01801A	37, 37,	37, 37, 39,	391, 391,	34, 34, 34,
EJBR01901Z	KIA	33800-4X500	DELL THIRDILL THIRD	THE PARTY OF THE PARTY OF
EJBR02101Z	RENAULT	8200240244		
EJBR02201Z	FORD (TRUCK/I	2T1Q9F593AA		Shaper Shaper Sh
EJBR02301Z	KIA	33800-4X500	15 15 1	1 35 35
EJBR02401Z	KIA	33800-4X800	September September 1	21/200, 21/200, 21/2
EJBR02501Z	Triple Triple 7	The Physics	1700 Tree 1700	Tries Tries
EJBR02601Z	SSANGYONG	A6650170121	28 St. 28 May .	24,000 34,000 34,
EJBR02801D	TKľA	33800-4X500	Min. Min. Min	THE THE .

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



EJBR02901D	KIA	33800-4X800	33801-4X800	
EJBR03001D	KIA	33800-4X900	and the state of the state of	Strain Strain
EJBR03101D	trace trace to	-1777 -1777	70 m	i mili
EJBR03401D	SSANGYONG	A6640170021	Stor. Stor.	21g 21g 21g

(2) Injector Control Valve's Part Number Common Writing

9308-618C, 9308618C, 9308 618C

1.3.9308-618C Injector Control Valve's Specifications and Dimensions

Injector Control Valve Size: 4cm*4 cm *3 cm Injector Control Valve Box Size: 7 cm *5 cm *3 cm Injector Control Valve Packing Size: 26 cm *10 cm

Injector Control Valve Net Weight: 0.03kg
Injector Control Valve Gross Weight: 0.05kg

Injector Control Valve Quality: China Made Brand New Injector Control Valve

MOQ: 4 Pieces

1.4.9308-618C Injector Control Valve's Quality Control

(1) Injector Control Valve Testing

All injector control valve spare parts are tested for electrical characteristics, accuracy, high temperature, low temperature, withstand voltage, leakage, durability, and various working conditions.

(2) Injector Control Valve Inspection

The factory inspection of the injector control valve is undergone full inspection, random inspection, and batch inspection three inspections. Different brands of test benches are used to test the same fuel injector control valve for a total of no less than three times for factory inspection, and injector control valve installation and test environment are progressed in dust-free workshop.

(3) Injector Control Valve Installation

When assembling the valve body and valve core of the control valve, we strictly follow the standard technical indicators of the gap between the valve body and the valve core to assemble so that to ensure that each control valve meets the factory standard and use standard.

1.5.9308-618C Injector Control Valve's Customized Service

(1) Injector Control Valve's Customized Service: Meet the customized needs of OEM manufacturers for control valve core, control valve body, part number lettering, QR code engraving, control valve box, VCI anti-rust bag and label customized etc,.

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

5 / 20





(2) Injector Control Valve's Customized Service Requirements:

Custom injector control valve cores are not less than 100 pieces.

Custom injector control valve bodies are not less than 100 pieces.

Custom injector control valve boxes are not less than 100 pieces.

The purchase of injector control valves are not less than 100 pieces.

The purchase of injector control valves engraving contents are not less than 100 pieces.

Customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file.

• Once the customized injector control valve is sold, it cannot be returned or exchanged if there is no quality problems.

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd



1.6.9308-618C Injector Control Valve's Packing List

(1) Injector Control Valve Spare Parts List



Minors are forbidden to use control valve, control valve fixture, control valve box and VCI anti-rust bag to avoid personal injury.

Control valve fixture, control valve box are recyclable accessories that can be reused.

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd



VCI anti-rust bag is non-degradable materials, please dispose of them properly

1.7.9308-618C Injector Control Valve's Warranty Instructions

(1) Injector Control Valve Warranty Conditions and Instructions

It is necessary to provide pictures, videos of injector control valve or test reports of injector control valve inspection equipment as evidence to feed back to the salesman.

Injector control valve abnormal conditions are properly explained such as: 1.Black smoke, 2. Engine shake, 3. Difficulty starting the engine, 4. Engine noise, 5. oil leakage etc.

Above problems also may cause by the incorrect installation of injector, if the problems are confirm to be product's problems after tested by Shumatt, it is within the warranty coverage.

(2) Injector Control Valve Warranty Coverage

After customers receive the 9308-618C injector control valve within 15 days , if there is a performance failure and the product has no appearance damage, customer can choose to replace it or repair it;

If the 9308-618C injector control valve has performance problems during the warranty period (3 months), and it is confirmed to be product's problems after being tested, you can contact our salesmen to replace the same model or a reworked product with the same performance for free;

If the injector control valve has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

▲ Tips: For products not within warranty period, our company can provide paid maintenance services. For products after paid repaired, the same performance problem will have a free warranty period within 3 months from the date of repairing.

(3) Injector Control Valve Out of Warranty Coverage

The injector control valve is artificially damaged due to assembly errors during the process of assembling. The warranty period has expired.

Injector injector control valve failure caused by high temperature, high pressure, humidity, rain and snow, saline-alkali land, earthquake, and used in abnormal environment.

Injector injector control valve damage caused by man-made reasons (throwing, strong magnetic field magnetization, set fire).

Injector injector control valve failure or injector damage caused by non-injector injector control valve's design, technology, manufacturing, quality and other issues.

Injector injector control valve failure due to system pressure exceeding system approved pressure.

Injector injector control valve failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.

Injector injector control valve failure caused by not installing according to the tightening torque specified in injector maintenance manual (the tightening torque is too large or too small).

Injector injector control valve failure caused by not following the installation angle specified in injector maintenance manual.

Injector injector control valve failure caused by not following the cleaning requirements specified in 0.300877 1777 CON 400ETT injector maintenance manual.

Injector injector control valve failure caused by failure to replace consumable parts as specified in injector maintenance manual.

1.8.9308-618C Injector Control Valve's Manufacturer

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com


98

Injector Control Valve's Manufacturer: Shenzhen Shumatt Technology Co., Ltd

2.9308-618C Injector Control Valve Technical Support

2.1.9308-618C Injector Control Valve's Inspection

(1) Check and see if there is fray on the sealing surface of control valve and the control valve core.



Pic No. 1

(2) Check whether the armature stroke (CRT220) of the control valve is within the range of 30~70μm. The lift of the armature will affect the fuel injection quantity at each point. The greater the armature lift, the greater the fuel injection volume, if the armature stroke is out of range, please replace control valve in time.



Pic No. 2

Mob/WhatsApp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133



2.2.9308-618C Injector Control Valve's Installation

- (1) Before install the orifice plate, clean it in an ultrasonic cleaning machine for 3-5 minutes so that to make the dirt, anti-rust oil oxide, paraffin base, naphthenic base, intermediate base, salt, lead naphthenate, zinc naphthenate, sodium petroleum sulfonate, barium petroleum sulfonate, calcium petroleum sulfonate, tallow diamine trioleate and rosin amine shedding fall off.
- (2) Use compressed air to clean up the cleaning fluid attached to the surface of the cleaned orifice plate to meet the use standard.
- (3) Place the injector solenoid valve into the injector house, see as Pic No.1



Pic No.1

(4) Put the solenoid valve spring adjustment shim into solenoid valve, see as Pic No.2



Pic No.2

Mob/WhatsApp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

 $\mathcal{G}^{(i)}$

98

98



Shenzhen Shumatt Technology Co., Ltd

(5) Put the solenoid valve spring into the solenoid valve, see as Pic No.3



Pic No.3

(6) Put the control valve core into the control valve, see as Pic No.4



Trine Trine, Trine.

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

 $\mathcal{G}_{ij}^{(k)}$



(7) Use the injector stroke measuring tool (CRT220) to measure whether the gap between the control valve and the armature is in the range of 30~70μm, see as Pic No.5



Pic No.5

Pic No.5

(8) Install the control valve in the injector house, see as Pic No.6



Pic No.6

Mob/WhatsApp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

THE THE PERSON STREET WITH STREET STREET STREET STREET

98

 $\mathcal{G}^{(0)}$



Shenzhen Shumatt Technology Co., Ltd

(9) Install the injector nozzle spacer on the control valve, see as Pic No.7



Pic No.7

(10) Put in the nozzle needle valve spring, see as Pic No.8



Pic No.8

THE THE THE

Mob/WhatsApp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

 $\mathcal{G}^{(i)}$

98

98



Shenzhen Shumatt Technology Co., Ltd

(11) Put the nozzle needle valve into the nozzle, see as Pic No.9



Pic No.9

(12) Install the nozzle on the injector, see as Pic No.10



Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

 $\mathcal{G}_{ij}^{(i)}$

 $\mathcal{G}_{\mathcal{A}_{p}}^{(p)}$

 $\mathcal{G}_{ij}^{(k)}$

THE THE THE THE

Website: www.shumatt.com



Shenzhen Shumatt Technology Co., Ltd

(13) Install the injector nozzle cap on the injector with a torque wrench (CRT084), torque is within 40-45Nm, see as Pic No.11



Pic No.11 (14) After installation, use a multi-meter (RTK199) to measure whether the resistance range of the injector solenoid valve is within (0.155 Ω –0.190 Ω), see as Pic No.12



Pic No.12

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com



(15) Insulation test. Test whether the injector is insulated from the shell, use (500v, 10M or higher voltage) for testing, see as Pic No.13



Pic No.13

(a) LEAK TEST

Test Result

1.The oil return is not sealed: Leakage between control valve and armature.

May Lead To:

1.Leaky oil return may lead to large oil return volume, the nozzle oil leakage and can not build up pressure, which cause to injector failure working.

Solution:

Check the control valve's sealing condition or change control valve.

2.3.9308-618C Injector Control Valve's Technical Support Obtaining Methods

- (1) Injector Control Valve Technical File, visit http://shumatt.com to get the technical file.
- (2) Injector Control Valve Technical Videos

Facebook: Visit https://www.facebook.com/hison.li to get the technical videos, constantly follow can get more information.

YouTube: Visit https://www.youtube.com/channel/UCByvYBx7VjV mAfxh Hu-aw to get the technical videos, constantly follow can get more information.

Shumatt: Visit http://shumatt.com to get the technical videos.

(3) Injector Control Valve Information Query Software

TruckBook Parts EPC APP, Android/Apple App Store download and install, visit http://shumatt.com to get the download and installation tutorial

(4) Search injector control valve test data through TruckBook Parts EPC APP.

3.9308-618C Injector Control Valve's Purchase and Delivery

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



3.1.9308-618C Injector Control Valve's Purchase Payment Terms

Payment Terms: T/T, PayPal, Alipay, WeChat

Please contact our salesmen for specific payment information.

3.2.9308-618C Injector Control Valve's Main Sales Markets

Injector control valve main sales markets: Asia, Europe, North America, South America, Africa etc.

3.3.9308-618C Injector Control Valve's Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

3.4.9308-618C Injector Control Valve's Shipping Ways

Destination in China areas: SF Express, Debon Express, the corresponding logistics company can be provided Olacio. according to customer requirements in special cases.

Destinations out of China's areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by

3.5.9308-618C Injector Control Valve's Lead time

Lead time: Send out within 3 - 7 working days after receiving payment (Except for special products and 38000

3.6.9308-618C Injector Control Valve's Logistics Time for Destination Out of China's Areas

DHL Logistics Time:

	Country or Region of Departure	Hong Kong, China	Other Countries or Regions of Asia	Australia and New Zealand	Europe	America	Other Countries
S	China's Mainland	7 Days	7 Days	8 Days	8 Days	8-12 Days	7-10 Days

UPS Logistics Time: Country or Region of Departure: China's Mainland

Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time
Japan	3 Days	UK	5-7 Days	Egypt	5-7 Days
Turkey	5-7 Days	Singapore	3 Days	Switzerland	5-7 Days
Bahrain	5-7 Days	Latvia	7-10 Days	New Zealand	7-10 Days
Sri Lanka	5-7 Days	Thailand	3 Days	Austria	5-7 Days
Romania	5-7 Days	Vietnam	3-5 Days	Estonia	5-7 Days
Malaysia	3-5 Days	Israel	5-7 Days	Mexico	7-10 Days
France	5-7 Days	America	5-7 Days	United Arab Emirates	5-7 Days
Italy	5-7 Days	Netherlands	5-7 Days	Bengal	7-10 Days
Lebanon	5-7 Days	Philippine	3-5 Days	Greece	7-10 Days
South Korea	3 Days	Spain	5-7 Days	Myanmar S	5-7 Days
Canada	5-7 Days	Germany	5-7 Days	Saudi Arabia	7-10 Days
Portugal	5-7 Days	Australia	5-7 Days	South Africa	7-10 Days
Denmark	5-7 Days	Belgium	5-7 Days	Ukraine	7-10 Days
India	7-10 Days	Qatar	7-10 Days	Poland	5-7 Days
Indonesia	3-5 Days	Morocco	7-10 Days	Pakistan	7-10 Days
Kuwait	7-10 Days	775m. 775m. 775m	Steen Page	the constitution of the constitution of	Mary Mary

The logistics time is for reference only, subjects are according to the actual arrival.

3.7.9308-618C Injector Control Valve's Packing

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com

 $\otimes \mathcal{H}^{0}$

 $\otimes \mathcal{V}^{\mathbb{N}}$

Shenzhen Shumatt Technology Co., Ltd

Domestic express packaging: Usually wrapped with waterproof scotch tape, such as picture No.1.

International express packaging: Wrapped with waterproof yellow tape After wrapping the black protective film, such as picture No. 2.

Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 4, Also, the products can be packaged according to customers' requirements.

▲ The packing tray is made of plastic and can be recycled.

▲ Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are non-degradable materials, please dispose of them properly.

Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film, and white wrapping protective film to avoid personal injury.



Pic No. 1

Domestic express packaging:

Wrapped by Transparent tape



International express packaging:
Wrapped with yellow tape after wrapping black protective film

Pic No. 2



Pic No. 3

Pallet Shipping: Use pallet that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties

4.9308-618C Injector Control Valve's Storage Standard

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



(1) Choose a suitable storage place

The warehouse and cargo yard where injector control valve is stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acid, alkali, salt and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry.

(2) Strict requirements of warehousing

Strict inspections should be carried out when injector control valves are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do anti-rust treatment in time. The packed injector control valves must be protected from being damaged.

(3) Keep the warehouse dry and preventing moisture

The relative humidity is usually below 70% for injector control valves placed in the room, and the corrosion of injector control valves is significantly reduced.

Injector control valves must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content.

(4) Stack Properly

After the injector control valve is exposed in rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the injector control valve from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse

If injector control valve package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

A It is forbidden to leave the injector control valve exposed in the air for a long time.

It is forbidden to store acid, alkali, salt and other substances together with the injector control valve.

■ The unpacked injector control valve must be rust-proof during secondary storage.



5.1. Company Introduction

Chinese Name: 深圳市舒马特科技有限公司

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

English Name: Shenzhen Shumatt Technology Co., Ltd.

Mob Phone/WeChat: +86-13410541523

☐ HK Telephone: +852-67653519

Telephone: +86-755+23215133

Email: ruby@shumatt.com

Website: www.shumatt.net

Shenzhen Office: 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway Station, Bao'an District, Shenzhen, China's Mainland

Shenzhen Office: Room 428-430, Building B, Huafeng Zhigu Technology Industrial Park, Exit B, Fuyong Metro Station, Bao'an District, Shenzhen, China's Mainland

Hong Kong Office: Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

After-sales Service Address: Please contact our salesmen to obtain and provide the corresponding product maintenance reasons (Reference: 1.7. 9308-618C Injector Control Valve's Warranty Instructions.)

5.2. Sales-men's Contact Information

No.	Name	WeChat/ WhatsApp	Email	Facebook	YouTube				
1	Ruby	+86-13410541523	ruby@shumatt.com	Hison Li	Hison Li				
2	lvy	+86-18025309821	sales@shumatt.com	Ivy Shumatt	Shumatt IVY				
3 7000	Rebecca	+86-18025349821	sales01@shumatt.com	Rebecca SHUMATT	SHUMATT Rebecca				
4	Janny	+86-18028749821	sales02@shumatt.com	Janny shumatt	Janny Shumatt				
5	Sam	+86-13316859821	Sales8@shumatt.com	Shumatt Sam	Sam Shumatt				
6	Natalie	+86- 18938945856	sales15@shumatt.com	Shumatt Natalie	Lin Natalie				
7	Ada an a	+86-1342286353	sales5@shumatt.com	Shumatt Ada	Ada Shumatt				
8	Hison Li	+86-18318811871	web@shumatt.com	Hison Li	Hison Li				
9	Mecca	+86-18938948618	sales11@shumatt.com	Shumatt Mecca	Shumatt Mecca				
10	Eric	+86 18319033618	sales3@shumatt.com	311 300 St. 200	98 98 98 P				
11	Wayne (Joaquín en español)	+86-13316959821	wayne@shumatt.com	shumattwayne	Wayne Shumatt				
12	Sylvia	+86 18312499884	sales6@shumatt.com	Salah Salah					
301	Visit http://www.shumatt.com to obtain the latest information of salesmen								
	PS: Shumatt's sales-men's emails are all end with @shumatt.com								

6. Copyright Statement

The copyright of any contents (including but not limited to parameters, data, text, charts, images, sound, videos, etc.) provided in "618C Series 9308-618C Injector Control Valve Technical File" belong to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify any contents in "618C Series 9308-618C Injector Control Valve Technical File" in any way. At the same time, any conditions to spread, re-post, display the contents of "618C Series 9308-618C Injector Control Valve Technical File" should indicate that the cited article is from Shenzhen Shumatt Technology Co., Ltd., Any actions failure to follow above conditions to use "618C Series 9308-618C Injector Control Valve Technical File" will violate the "Copyright Law of the People's Republic of China" and other laws and regulations and the provisions of relevant international conventions.

Mob/WhatsApp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com