


F00VC01359 Injector Valve Assembly Technical File



Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd



F00VC01359 Injector Valve Assembly Technical File

Content

1. F00VC01359 Injector Valve Assembly's Introduction	2
1.1.F00VC01359 Injector Valve Assembly's Basic Information	2
1.2.F00VC01359 Injector Valve Assembly's Application Information for Injectors	
1.4.F00VC01359 Injector Valve Assembly's Quality Control	8
1.5.F00VC01359 Injector Valve Assembly's Customized Service	8
1.6.F00VC01359 Injector Valve Assembly's Packing List	
1.7.F00VC01359 Injector Valve Assembly's Warranty Instructions	9
1.8.F00VC01359 Injector Valve Assembly's Manufacturer	10
2.F00VC01359 Injector Valve Assembly Technical Support	
2.1.F00VC01359 Injector Valve Assembly's Installation Precautions	10
2.2.F00VC01359 Injector Valve Assembly Replacement Conditions	11
2.3.F00VC01359 Valve assembly Technical Support Obtaining Methods	
3.F00VC01359 Valve Assembly's Purchase and Delivery	12
3.1.F00VC01359 Valve Assembly Purchase Payment Terms	12
3.2.F00VC01359 Valve assembly's Main Sales Market.	12
3.3.F00VC01359 Valve assembly's Declaration Requirements	12
3.4.F00VC01359 Valve Assembly's Shipping Ways	12
3.5.F00VC01359 Valve Assembly's Lead Time	12
3.6.F00VC01359 Valve Assembly's Logistics Time for Destination Out of China's Areas	13
3.7.F00VC01359 Valve Assembly's Packing	13
4.F00VC01359 Valve Assembly's Storage Standard	14
5. Company Information	15
5.1. Company Introduction	15
After-sales Service Address: Please contact our salesmen to obtain and provide the corre	esponding
product maintenance reasons (Reference: Injector Warranty Instructions)	15
5.2. Sales-men's Contact Information	
6. Copyright Statement	16

Mob/Whatsapp: +86 13410541523Tel: +8675523215133Email: ruby@shumatt.comWebsite: www.shumatt.com



1. F00VC01359 Injector Valve Assembly's Introduction

1.1.F00VC01359 Injector Valve Assembly's Basic Information

Title	China made brand new fuel injector valve assembly F00VC01359
SKU1	G1S8F00VC01359
SKU2	G1F1F00VC01359/F10000B2BC01359
SKU3	G1F2F00VC01359/F20000B2BC01359 (High quality)

1.2.F00VC01359 Injector Valve Assembly's Application Information for Injectors

(1) F00VC01359 Injector Valve Assembly's Car Model Matching Information

Injector Part Number	Car Number	OE Number	OE Number	OE Number	
0 445 110 305	JMC (JIANGLING)	1112100CAT			
0 445 110 313	FOTON (BEIJING FUTIAN ENVIR.)	J0445110313A7 596			
0 445 110 332	GREAT WALL	1112100-E05			
0 445 110 335	JENS & CATTEL	1100200FA040			
0 445 110 343	JENS & CATTEL	1100200FA080			
0 445 110 344					
0 445 110 345	YANGCHAI (YANGZHOU DIESEL ENG)	2014355			
0 445 110 346	QUANCHAI (ANHUI QUANCH. POWER)	4D22E41000			
0 445 110 347	QUANCHAI (ANHUI QUANCH. POWER)	4D22E41000			
0 445 110 355	FAW	1112100-D02			
0 445 110 357					
0 445 110 364					
0 445 110 365					
0 445 110 379					
0 445 110 380	GONOW	1112300-40300			
0 445 110 395	FAW	1112100B35			
0 445 110 397					
0 445 110 404	GREAT WALL	1112100-E06- A1			
0 445 110 407	GREAT WALL	1112100-E06- A1			
0 445 110 412	PIAGGIO	889478			

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



	• • SHETIZH	en Shumatt	10011101069	20., Lta	
0 445 110 416					
0 445 110 417	QUANCHAI (ANHUI QUANCH. POWER)	3408022510000			
0 445 110 427					
0 445 110 445					
0 445 110 446					
0 445 110 448					
0 445 110 449	QUANCHAI (ANHUI QUANCH. POWER)	4408522510000			
0 445 110 454	JMC (JIANGLING)	11112100ABA			
0 445 110 462	GONOW	1112300-40305			
0 445 110 465					
0 445 110 466	JAC (JIANGHUAI AUTOMOBILE)	1100200FA130			
0 445 110 481					
0 445 110 509					
0 445 110 512					
0 445 110 515					
0 445 110 516	YANGCHAI (YANGZHOU DIESEL ENG)	2014994			
0 445 110 517	YANGCHAI (YANGZHOU DIESEL ENG)	2100626			
0 445 110 521					
0 445 110 531	FOTON (BEIJING FUTIAN ENVIR.)	E049332000065			
0 445 110 533					
0 445 110 537					
0 445 110 539	JMC (JIANGLING)	CN1-9K546-A1A			
0 445 110 541	FAW	1112100AB81- 0000			
0 445 110 549					
0 445 110 623					
0 445 110 628					
0 445 110 629	JMC (JIANGLING)	1112100ABYB1			
0 445 110 630	JMC (JIANGLING)	DP1-9K546-AA			
0 445 110 631	JMC (JIANGLING)	DP1-9K546-AA			

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com © 2022 Shenzhen Shumatt Technology Co., Ltd



0 445 110 669				
0 445 110 670	JAC (JIANGHUAI AUTOMOBILE)	1100200FA040B J-1		
0 445 110 672				
0 445 110 691	FOTON (BEIJING FUTIAN ENVIR.)	E049332000113		
0 445 110 710	JMC (JIANGLING)	1100200FA171		

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com Website: www.shumatt.com



(2) F00VC01359 Injector Valve Assembly's Application for Injectors' Part Number

Injector Series	Injector Part Number	System Pressure	Re-manufactured Part Number	System Pressure	Universal Number	System Pressure	Universal Number	System Pressure	Universal Number
CRI2-14	0 445 110 305	1400	0 986 435 231	-20	arts arts	off of	775	200	
CRI2-14	0 445 110 313	1400	abra, abra,	Sky Sky	den d	D. Sim.	align. align	21/2	
CRI2-14	0 445 110 332	C AMPLY A	ONT A SHITT A SHITT	- CONT CO.	OT A SOME	CONTE A SOUT	T A STATE A ST	N. C.	
CRI2-14	0 445 110 335	1400	34.	31. 31.	0 445 110 512	1400	34. 34.	360	
CRI2-14	0 445 110 343	1400	THE THE SPECIAL SPECIA	SHUTTERT SHUTT	0 445 110 412	1400	SHADON'S SHAD	2/6	
CRI2-14	0 445 110 344	4 4	1 1 1	-15	at at	35 3	1 4	A .	
CRI2-14	0 445 110 345	1400	Street, Street,	210201 21020	0 445 110 344	FIGH. PHON.	Shran, Shra	276	
CRI2-14	0 445 110 346	T . WITT	entr agent agent	-00771 -00	0 445 110 347	white whi	TOTAL TO	157	
CRI2-14	0 445 110 347	54" 94"	31, 31,	31. 31.	0 445 110 346	90	31 31	Sign	
CRI2-14	0 445 110 355	1400	DALLA BERTALLA SEGUELLA	CARLELL CARL	ALL STREET	AUTOMIC STATES	SHADOWEL SHAD	ett.	
CRI2-14	0 445 110 357	4 -45	-d -d -d		4 4		2402	VX.	
CRI2-14	0 445 110 364	1400	Day Elgister, Elgister	SATURE SATU	0 445 110 365	May Stray	SHADOW, SHADO	2/4	
CRI2-14	0 445 110 365	The same	OTT - MITT - MITT		0 445 110 364	1400	Triber 7	art.	
CRI2-14	0 445 110 379	1400	24, 24,	SI SI.	8000 8	800	2500	217	
CRI2-14	0 445 110 380	1400	SALL STRUCT	SHAREST TEN	0 445 110 379	1400	THE PROPERTY STATES	MIT SHE	
CRI2-14	0 445 110 395	4 2				120	6 26	24	
CRI2-14	0 445 110 397	1400	SALESAN SALESAN	SISTERN SISTER	SPIDING	1000 PH2000	SHADON, SHAD	2/8	
CRI2-14	0 445 110 404	7	att att att	24	0 445 110 407	1400	1	15%	

Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

SHUMATT

Shenzhen Shumatt Technology Co., Ltd

CRI2-14	0 445 110 407	1400	0 445 110 404
CRI2-14	0 445 110 412	1400	0 445 110 343 1400
CRI2-14	0 445 110 416	1400	0 445 110 417 1400
CRI2-14	0 445 110 417	1400	0 445 110 416 1400
CRI2-14	0 445 110 427	SATISTICAL THE SALL STATISTICAL STATISTICA	0 445 110 426 1400
CRI2-14	0 445 110 445	1400	0 445 110 446 1400
CRI2-14	0 445 110 446	1400	0 445 110 445 1400
CRI2-14	0 445 110 448	1400	0 445 110 449 1400
CRI2-14	0 445 110 449	1400	0 445 110 448 1400
CRI2-16	0 445 110 454	1600	SALES STREET,
CRI2-14	0 445 110 462	1400	0 445 110 481 1350
CRI2-16	0 445 110 465	1600	0 445 110 466 1600
CRI2-16	0 445 110 466	1600	0 445 110 465 1600
CRI1-13	0 445 110 481	1350	0 445 110 462 1400
CRI2-16	0 445 110 509	CATALL PATERLE SHELL SHELL SHELL SHELL	SATELLE STREET, STREET
CRI2-14	0 445 110 512	1400	0 445 110 335 1400
CRI2-16	0 445 110 515	1600	Strain Strain Strain Strain Strain Strain Str
CRI2-16	0 445 110 516	1600	STATE OF THE PERSON NAMED ASSOCIATION OF THE PERSON OF THE
CRI2-16	0 445 110 517	1600	su su su su su su

Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133



					-			
CRI2-14	0 445 110 521	1400	-ri -ri -ri	20	er 20	Let Le	2365	ed.
CRI2-16	0 445 110 531	1600	Mr. 2017 and 2017 and	SUPPLIES SUPPLIES	Slope S	Page Styles	SUNTANCE SUNTA	3/6
CRI2-16 OHW	0 445 110 533	1600	THE THE THE	The state	The same	Trees.	77700.7	er.
CRI2-16	0 445 110 537	1600	20,000	36	8000	97	2500 3500	24,
CRI2-16	0 445 110 539	1600	SPITT THE STREET, THE SPINISH	SALES THE SALES	0 445 110 538	1600	THE THEFT WAS	ALL AR
CRI2-16	0 445 110 541	1,600		- E		11.22		
CRI2-16	0 445 110 549	Strang Stra	SATURE SATURAL	SATURAL SATUR	0 445 110 548	Fillian Astron.	Strang Strang	No. 24s.
CRI2-16	0 445 110 623	1600	art art art		m m	art's art	1	100
CRI1-16	0 445 110 628	1600	0 986 435 334	Store Store	0 445 110 629	1600	stra. stra	27/6
CRI1-16	0 445 110 629	1600	0 986 435 334	- BUTTER - BUTTER	0 445 110 628	1600	1 . 3.55 T. 1	NTT TO
CRI1-16	0 445 110 630	1600	0 986 435 326		0 445 110 631	1600	300 300	3.
CRI1-16	0 445 110 631	1600	0 986 435 326	STREET, STREET	0 445 110 630	1600	2182000 21820	218
CRI1-13	0 445 110 669	T	Titon Filton Titon	marr m	0 445 110 670	1400	171100 2	arr .
CRI2-14	0 445 110 670	1400	SUS, SUS	Elga, Elga,	0 445 110 669	SV	2lyn 2lyn	510
CRI1-16	0 445 110 672	1600	SPTT - ASSISTED - ASSISTED	AND THE PARTY OF T	THE WAY THE	AUTOTIT - AUTOTIT	" 177477 LOS	MITT.
CRI1-16	0 445 110 691	1600	-	n - 20	0 445 111 016	30	30' 30'	30
CRI1-16	0 445 110 710	1600	PALL PARTIES.	SHARRING SHARR	C. Strategier, St.	STEEL PASSES	SPASTALL SPAST	N. SH.

Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

(3) F00VC01359 Injector Assembly Part Number Common Writing

F00VC01359, F00VC01359, F 00V C01 359, F 00V C01 359, F00V C01 359, F00V C01 359, F00VC01 359, FOOVC01 359, F 00V C01359, F OOV C01359, F 00VC01359, F OOVC01359, F00V C01359, FOOV C01359

1.3.F00VC01359 Injector Valve Assembly's Specifications and Dimensions Parameters

Valve Assembly Size: 13 cm*2 cm *2 cm Valve Assembly Box Size: 14 cm *3 cm *3 cm Valve Assembly Packing Size: 31 cm *12 cm

Valve Assembly Net Weight: 0.03kg Valve Assembly Gross Weight: 0.03kg

Valve Assembly Quality: China Made Brand New Injector Valve Assembly

Valve Assembly MOQ: 4 PCS

1.4.F00VC01359 Injector Valve Assembly's Quality Control

(1) Valve Assembly Testing

All parts of the injector valve assembly are subjected to precision testing, high temperature testing, low temperature testing, withstand pressure testing, leakage testing, durability testing, and various working conditions testing.

(2) Injector Valve Assembly Inspection

The factory inspection of the injector valve assembly is undergone full inspection, random inspection, and batch inspection three inspections. Different brands of test benches are used to test the same injector valve assembly for a total of no less than three times for factory inspection, and the fuel injector installation testing environment are progressed in dust-free workshop.

(3) Injector Valve Assembly Installation

When matching the valve cap and valve steam, Shumatt strictly complies with the standard of valve cap and valve stem clearance technical indicators to ensure that each valve assembly meets the factory standards and use standards.

1.5.F00VC01359 Injector Valve Assembly's Customized Service

(1) Valve Assembly's Customized Service: Meet the customized needs of OEM manufacturers for shell lettering, logo engraving, injector internal packaging, injector external packaging and labels customized, etc

lettering, logo engraving, injector inte	ernal packaging, injector external packaging and labels customized, etc.
St 20 30 30 St	
Valve Cap Color Customized 1000 pieces (White color is optional)	Valve Cap Color Customized 1000 pieces (Purple and red color are optional) Valve Cap Groove Customized
	STATE OF THE STATE
si si	No.
Valve Cap Lettering Valve Cap logo Engraving Valve Cap QR Code Engraving	Valve Assembly Box (Square is optional) Valve Assembly Box (Cylindrical is optional)

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



S481	I igh	HOA ACC	ET ST	TOTAL .	SHUMATT F00/001379 Common rail valve Application: 0445110354 0445110424 F100008128-01379 ***********************************	28.35%	ET SHAMMET SHAMMET SHAMMET SHA
	Valve Assembly Bag			Valve Assembly Label 7cm*5cm			/

(2) Valve Assembly's Customized Service Requirements:

Customized valve assembly box are no less than 100 pieces.

Customized valve assembly groove no less than 100 pieces.

The purchased of customized valve assembly are no less than 1000 pieces.

The purchased of customized valve cap engraving contents are no less than 1000 pieces.

The purchased of customized valve colors are no less than between 1000 -10000 pieces.

Customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file.

▲ Once the customized injector valve assembly is sold, it can not be returned or exchanged if there is no quality problems. □

1.6.F00VC01359 Injector Valve Assembly's Packing List

(1) Valve Assembly's spare parts list

Serial Number	1	2	3
Image	i shumst	SALES SALES	
Name	Injector Valve Assembly	Valve Assembly Anti-rust Paper	Valve Assembly Box (Square is optional)
Description	Valve Assembly Part Number F00VC01359	Prevent the valve assembly from rusting	Protect the valve assembly from being damaged by colliding
Serial Number	4	5	Ston. Ston. Ston. Sto.
Image		yci	/
Name	Valve Assembly Box (Cylindrical is optional)	VCI Anti-rust Bag	TT ANT ANT ANT
Description	Protect the valve assembly from being damaged by colliding	Prevent the valve assembly from rusting	

Minors are prohibited from using the injector valve assembly, valve assembly anti-rust paper, valve assembly box, and VCI anti-rust bag to avoid personal injury.

▲ The valve assembly box is recyclable and can be reused.

VCI anti-rust bag is non-degradable material, please dispose of it properly after use.

1.7.F00VC01359 Injector Valve Assembly's Warranty Instructions

(1) . Valve Assembly Warranty Conditions and Instructions

It is necessary to provide pictures, videos, or test reports detected by the injector valve assembly inspection equipment when the valve assembly is abnormal during use as evidence to feed back to the

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



salesman.

Abnormal conditions are properly explained such as: 1.Smoke, 2. Engine shake, 3. Difficulty starting the engine, 4. Engine noise, 5. oil leakage etc.

(2) . Valve Assembly Warranty Coverage

Within 15 days after customer receives the **F00VC01359** injector valve assembly, if there is a performance failure and the product has no appearance damage, customer can choose to replace it or repair it;

If the **F00VC01359** injector valve assembly has performance problems during the warranty period (3 months), and it is confirmed that it is product's problems after testing, you can contact our salesmen to replace the same model or a reworked product with the same performance for free;

If the injector house has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

(3) . Injector Valve Assembly Out of Warranty Coverage

The warranty period has expired.

Injector valve assembly failure caused by high temperature, high pressure, humidity, rain and snow, saline-alkali land, earthquake, and used in abnormal environment.

Injector valve assembly damage caused by man-made reasons (throwing, strong magnetic field magnetization, set fire).

Injector valve assembly failure or injector damage caused by non-injector design, technology, manufacturing, quality and other issues.

Injector valve assembly failure due to system pressure exceeding system approved pressure.

Injector valve assembly failure caused by system voltage exceeding approved voltage.

Injector valve assembly failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.

Injector valve assembly failure caused by not installing according to the tightening torque specified in the vehicle engine maintenance manual (the tightening torque is too large or too small).

Injector valve assembly failure caused by not following the installation angle specified in the injector maintenance manual.

Injector valve assembly failure caused by not following the cleaning requirements specified in the injector maintenance maintenance manual.

Injector valve assembly failure caused by failure to replace consumable parts as specified in the injector maintenance manual.

1.8.F00VC01359 Injector Valve Assembly's Manufacturer

Injector Valve Assembly's Manufacturer: Shenzhen Shumatt Technology Co.,Ltd

2.F00VC01359 Injector Valve Assembly Technical Support


2.1.F00VC01359 Injector Valve Assembly's Installation Precautions

- (1) Clean the injector valve assembly in an ultrasonic cleaner for 3-5 minutes before installation, so as to make the stains, dust, rust-proof oil oxides, paraffin base, naphthenic base, intermediate base, salt, lead naphthenate, zinc naphthenate, sodium petroleum sulfonate, barium petroleum sulfonate, calcium petroleum sulfonate, tallow diamine trioleate, rosinamine on the surface of the valve assembly fall off.
- (2) Use compressed air to clean the cleaning fluid attached to the surface of the valve assembly after cleaning, and clean it up to the standard of use, as below
- (3) When installing the valve stem, make sure that the valve stem and the bonnet must ensure that the valve stem can move smoothly in it. as below


Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: <u>ruby@shumatt.com</u> Website: <u>www.shumatt.com</u>





(4) When installing the valve stem, make sure that the valve stem and the bonnet must ensure that the valve stem can move smoothly in it. as below




If the injector steel ball and the ball seat are not installed in accordance with the standard, it may cause serious damage to the injector valve assembly

2.2.F00VC01359 Injector Valve Assembly Replacement Conditions

(1) Valve Cap

Under the microscope, magnify 20 times to check that the oil inlet hole of the valve cap and the oil return hole of the bonnet are not worn, grooved, scratched, damaged, rusted or dented.



The wear of the top oil return hole causes the oil return to be too large and the leaking injector cannot inject oil

⚠ The side inlet hole is blocked causing the injector to establish the pressure chamber and the injector to function normally

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com




A Wear of the c

Wear of the cap cavity can cause the injector to work properly when the injector is badly delayed.

(2) Valve Rod

Microscope amplification 20 times, check the valve rod for wear, not smooth surface color, rust



The excessive clearance between the stem wear and the housing and between the cap causes an injector delay

A The valve stem lag will cause the injector to start the solenoid to start, and the oil needle can not return quickly after the nozzle is opened

• Check the injector components before replacing the injector valve assembly according following the injector service manual to avoid further damage to the injector valve assembly.

2.3.F00VC01359 Valve assembly Technical Support Obtaining Methods

- (1) Valve assembly Technical fail, visit http://shumatt.com to get the technical File
- (2) Injector Technical Videos

Facebook: Visit https://www.facebook.com/hison.li constantly follow can get more information.

YouTube: https://www.youtube.com/channel/UCByvYBx7VjV mAfxh Hu-aw to get the technical videos, constantly follow can get more information.

Shumatt: Visit http://shumatt.com to get the technical videos.

(3) Valve Assembly Information Query Software

TruckBook Parts EPC APP, Android/Apple App Store download and install, visit http://shumatt.com to get the download and installation tutorial

(4) Search The valve assembly test data through TruckBook Parts EPC APP.

3.F00VC01359 Valve Assembly's Purchase and Delivery.

3.1.F00VC01359 Valve Assembly Purchase Payment Terms

Payment Terms: T/T, PayPal, Alipay, WeChat

Please contact our salesmen for specific payment information.

3.2.F00VC01359 Valve assembly's Main Sales Market.

Valve assembly main sales markets: Asia, Europe, North America, South America, Africa etc.

3.3.F00VC01359 Valve assembly's Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

3.4.F00VC01359 Valve Assembly's Shipping Ways

Destination in China areas: SF Express, Debon Express, the corresponding logistics company can be provided according to customer requirements in special cases.

Destinations out of **China's** areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers.

3.5.F00VC01359 Valve Assembly's Lead Time

Lead time: Send out within 3-7 working days after receiving payment (Except for special products and special cases).

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133
Email: ruby@shumatt.com Website: www.shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

12 / 17



3.6.F00VC01359 Valve Assembly's Logistics Time for Destination Out of China's Areas

DHL Logistics Time:

Country or Region of Departure	Hong Kong, China	Other Countries or Regions of Asia	Australia and New Zealand	Europe	America	Other Countries
China's Mainland	7 Days	7 Days	8 Days	8 Days	8-12 Days	7-10 Days

UPS Logistics Time: Country or Region of Departure: China's Mainland

Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time
Japan	3 Days	UK	5-7 Days	Egypt	5-7 Days
Turkey	5-7 Days	Singapore	3 Days	Switzerland	5-7 Days
Bahrain	5-7 Days	Latvia	7-10 Days	New Zealand	7-10 Days
Sri Lanka	5-7 Days	Thailand	3 Days	Austria	5-7 Days
Romania	5-7 Days	Vietnam	3-5 Days	Estonia	5-7 Days
Malaysia	3-5 Days	Israel	5-7 Days	Mexico	7-10 Days
France	5-7 Days	America	5-7 Days	United Arab Emirates	5-7 Days
Italy	5-7 Days	Netherlands	5-7 Days	Bengal	7-10 Days
Lebanon	5-7 Days	Philippine	3-5 Days	Greece	7-10 Days
South Korea	3 Days	Spain	5-7 Days	Myanmar	5-7 Days
Canada	5-7 Days	Germany	5-7 Days	Saudi Arabia	7-10 Days
Portugal	5-7 Days	Australia	5-7 Days	South Africa	7-10 Days
Denmark	5-7 Days	Belgium	5-7 Days	Ukraine	7-10 Days
India	7-10 Days	Qatar	7-10 Days	Poland	5-7 Days
Indonesia	3-5 Days	Morocco	7-10 Days	Pakistan	7-10 Days
Kuwait	7-10 Days	24. 24.	20.	24. 24. 24.	34

The logistics time is for reference only, subjects are according to the actual arrival.

3.7.F00VC01359 Valve Assembly's Packing

Domestic express packaging: Usually wrapped in waterproof scotch tape, such as picture No.2.

International express packaging: Wrapped with waterproof yellow tape After wrapping the black protective film, such as picture No. 3.

Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 4, Also, the products can be packaged according to customers' requirements.

⚠ The packing tray is made of plastic and can be recycled.

⚠ Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are non degradable materials, please dispose of them properly.

Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film, and white wrapping protective film to avoid personal injury.

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com






Pic No.1

Domestic express packaging:

Wrapped by Transparent tape black protective film



Pic No.2

International express packaging:

Wrapped with yellow tape after wrapping



Pic No.3

Pallet Shipping: Use pallet that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties

4.F00VC01359 Valve Assembly's Storage Standard

(1) Choose a suitable storage place

The warehouse and cargo yard where the fuel injector is stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acids, alkalis, salts and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry.

(2) Strict requirements of warehousing

Strict inspections should be carried out when the fuel injectors are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do anti-rust treatment in time. Packaged injectors must be protected from damage.

(3) Keep the warehouse dry and preventing moisture

The relative humidity is usually below 70% for the fuel injectors placed in the room, and the corrosion of the fuel injectors is significantly reduced.

Injectors must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content.

(4) Stack Properly

After the injector is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the injector from rainwater and humid air, so the warehouse window should be checked

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



in time to avoid rainwater entering the warehouse

If the fuel injector package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

It is forbidden to leave the injector exposed in the air for a long time.

It is forbidden to store acids, alkalis, salts and other substances together with the injector.

The unpacked fuel injector must be rust-proof during secondary storage.

5. Company Information



5.1. Company Introduction

Chinese Name: 深圳市舒马特科技有限公司

English Name: Shenzhen Shumatt Technology Co., Ltd

Mob Phone/WeChat: +86-13410541523

HK Telephone: +852-67653519
Telephone: +86-755-23215133
Email: ruby@shumatt.com
Website: www.shumatt.net

Shenzhen Office: 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway

Station, Bao'an District, Shenzhen, China's Mainland

Shenzhen Office: Room 428-430, Building B, Huafeng Zhigu Technology Industrial Park, Exit B, Fuyong

Metro Station, Bao'an District, Shenzhen, China's Mainland

Hong Kong Office: Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

After-sales Service Address: Please contact our salesmen to obtain and provide the corresponding product maintenance reasons (Reference: Injector Warranty Instructions)

5.2. Sales-men's Contact Information

O'E' OWLOO MAN O CONSERVE MICE MAKEEUM					
No.	Name	WeChat/ WhatsApp	Email	Facebook	YouTube
1	Ruby	+86-13410541523	ruby@shumatt.com	Hison Li	Hison Li
2	lvy	+86-18025309821	sales@shumatt.com	Ivy Shumatt	Shumatt IVY
3	Rebecca	+86-18025349821	sales01@shumatt.com	Rebecca SHUMATT	SHUMATT Rebecca
4	Janny	+86-18028749821	sales02@shumatt.com	Janny shumatt	Janny Shumatt
5	Sam	+86-13316859821	Sales8@shumatt.com	Shumatt Sam	Sam Shumatt

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133
Email: ruby@shumatt.com Website: www.shumatt.com



6	Natalie	+86- 18938945856	sales15@shumatt.com	Shumatt Natalie	Lin Natalie
7	Ada	+86-1342286353	sales5@shumatt.com	Shumatt Ada	Ada Shumatt
8	Hison Li	+86-18318811871	web@shumatt.com	Hison Li	Hison Li
9	Mecca	+86-18938948618	sales11@shumatt.com	Shumatt Mecca	Shumatt Mecca
10	Eric	+86 18319033618	sales3@shumatt.com		
11	Wayne (Joaquín en español)	+86-13316959821	wayne@shumatt.com	shumattwayne	Wayne Shumatt
12	Sylvia	+86 18312499884	sales6@shumatt.com	43777	SHALL SHA

Visit http://shumatt.com to obtain the latest information of salesmen

PS: Shumatt's sales-men's emails are all end with @shumatt.com

6. Copyright Statement

The copyright of any contents "FOOVCO1359 Valve assembly Technical File" (including but not limited to parameters, data, text, charts, images, sounds or videos, etc.) provided in "F00VC01359 Valve assembly Technical File" belong to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify any contents in "F00VC01359 Valve assembly Technical File" in any way. At the same time, any conditions to spread, re-post, display the contents of "FOOVCO1359 Valve assembly Technical File" should indicate that the cited article is from Shenzhen Shumatt Technology Co., Ltd., Any actions failure to follow above conditions to use "F00VC01359 Valve assembly Technical File" will violate the "Copyright Law of the People's Republic of China" and other laws and regulations and the provisions of relevant international conventions.

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com Website: www.shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

16 / 17