SHUMAT

SHUMATT

SHUMATT

SHUM.

TIM

SHUM.

SHUMI

SHUMPTT SHUMPTT

Injector Solenoid Valve 294701-0145 Technical File

SHUMATT

UMFITT

SHUMATT

SHUMATT

3h

SA

Sh

SKU: G1B202943000140



SHUME SHUME SHUME SHUME SHUME

דוקות דוקות דוקות היאות הי

SHUMIT.

SPLIDET SPLEAS SPUTT SPERME Shenzhen Shumatt Technology Co., Ltd. SHUMATT

SILUDIA

SPURAT

 $\mathcal{G}^{(2)}$

Injector Solenoid Valve 294701-0145 Technical File

| 1. 294701-0145 Injector Solenoid Valve Introduction | с ⁴ , |
|--|---------------------------|
| 1.1. 294701-0145 Injector Solenoid Valve Basic Information | |
| 1.2. 294701-0145 Injector Solenoid Valve Common Part Number | ¢ |
| 1.5. 294701-0145 Injector Solenoid Valve Quality Control | |
| 1.6. 294701-0145 Injector Solenoid Valve Customization Service | Ċ. |
| 1.7. 294701-0145 Injector Solenoid Valve Packaging List And Packaging Dimensions | ٠, |
| 1.8. 294701-0145 Injector Solenoid Valve Testing Standards and Certificates | |
| | 2 |
| 1.9. 294701-0145 Injector Solenoid Valve Warranty Instructions | 1.1 |
| 1.10. 294701-0145 Injector Solenoid Valve Manufacturer | |
| 2. 294701-0145 Injector Solenoid Valve Technical Support8 | |
| 2.1. 294701-0145 Injector Solenoid Valve Utilized Location 2.2. 294701-0145 Injector Solenoid Valve Installation | 0 |
| | |
| 2.3. Reasons of 294701-0145 Injector Solenoid Valve Not Working Normally | |
| 2.4. Causes of 294701-0145 Injector Solenoid Valve Being Damaged | 65 |
| 2.5. 294701-0145 Injector Solenoid Valve Technical Support Obtaining Methods | |
| 3. 294701-0145 Injector Solenoid Valve Purchase And Delivery | |
| 3.1. 294701-0145 Injector Solenoid Valve Purchase And Payment Term | $\mathbb{C}^{\mathbb{N}}$ |
| 3.1. 294701-0145 Injector Solenoid Valves Main Sales Markets | |
| 3.3. 294701-0145 Injector Solenoid Valve Declaration Requirements | |
| 3.4. 294701-0145 Injector Solenoid Valve Shipping Ways | ĊĬ. |
| 3.5. 294701-0145 Injector Solenoid Valve Delivery Time11 | |
| 3.6. 294701-0145 Injector Solenoid Valve Logistics Time for Destination Out of China's Areas | |
| 3.7. 294701-0145 Injector Solenoid Valve Shipping Package | eŝ. |
| 4. 294701-0145 Injector Solenoid Valve Storage Standards | ٠, |
| 5. Company Information | |
| 5.1. Company Introduction | лċ. |
| 5.1. Company Introduction | 1.4 |
| 6. Copyright Statement | |

SPECTRO

SPREED

12000

SHORE

STRING

UNIT S

51^{0,000}

SPLER

SRUDAT

-51^{0,000}

9.10¹⁶

1.500

-98⁻³⁰ Mob/Whatsapp: +86 13410541523 Email :ruby@shumatt.com © 2022 Shenzhen Shumatt Technology Co., Ltd. 1/16

SPANORT

. 199⁵⁵

Tel: +8675523215133 Website : www.shumatt.com

 $g^{(p)}$

3.50⁵⁶

SP.SP

 $\wp^{\mathbb{R}}$

Å

 φ^{0}

 $\varphi_{i}^{(k)}$

 $\otimes^{\mathbb{R}}$

 ϕ^{0}

 ϕ^{0}

 ϕ_{i}^{R}

. 100⁰¹⁵

Injector Solenoid Valve 294701-0145 Technical File

1. 294701-0145 Injector Solenoid Valve Introduction

1.1. 294701-0145 Injector Solenoid Valve Basic Information

4,5⁹²⁴⁷

st^{yti}

| | Title | China Made New G2 Series Injector Solenoid Valve 294701-0145 |
|----|-------|--|
| j. | SKU | G1B202943000140 |

1.2. 294701-0145 Injector Solenoid Valve Common Part Number (1) Injector Solenoid Valve Applicable for Injector Model

| Injector Part Number | OE Number | OE Number | OE Number |
|----------------------|-------------|-------------------|---------------|
| 294701-0145 | 095000-9800 | 095000-8970 | 095000-8933 |
| 095000-5471 | 095000-8170 | 095000-6390 | 095000-6376 |
| 095000-5500 | 095000-5362 | 095000-5353 | 095000-5344 |
| 095000-5010 | 095000-0660 | 095000-8980 | 095000-8793 |
| 095000-8633 | 095000-6650 | 095000-6300 | 095000-6270 |
| 095000-5980 | 095000-5516 | 095000-8910 | 095000-8011 |
| 095000-6701 | | store store store | site (site si |

| Vehicle brand | Car Model | Engine Model | Batch Production Date |
|-------------------------|----------------------------------|--------------|------------------------|
| Can Trail and Trail and | FORWARD, INDUSTRIAL, N SERIES | 4H07 | 1004 |
| 897 297 297. | N SERIES | 4HK1 | 0310 |
| LANDAL SADAL | FORWARD | 6HK1 | 0607 |
| per per per | N SERIES | 6HL1 | 0310 |
| TOPOLOGICE STRUCTURES | FORWARD | 6H04 | 0401 |
| | N SERIES | 4HJ1 | 0206 |
| SHIDN SHIDN SHI | GIGA | even sources | 34 ⁰⁰⁰ 0609 |
| | N SERIES | 6WG1 | 0601 |
| 2011 21 STATE 27.5 | TRACTOR | 6081T 3100 | Star 0011 |
| | TRUCK | WD615 | 0610, 0901 |

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd. 2 / 16

Tel: +8675523215133 Website : <u>www.shumatt.com</u>

sa^{hiji}

505⁵⁷

(3) Injector Solenoid Valve's Common Writing Methods 095000-9800,095000-8970,095000-8933,095000-8903,095000-5471,095000-8170,095000-6390, 095000-6376,095000-6363,095000-5500,095000-5362,095000-5353,095000-5344,095000-5010, 095000-0660,095000-8980,095000-8793,095000-8633,095000-6650,095000-6300,095000-6270, 095000-5980,095000-5516,095000-8910,095000-8011,095000-6701,8-98219181-0,8-98151856-3, 8-98160061-3,8-98151837-3,8-97329703-2,8-98121163-2,8-97609791-5,8-97609789-6,8-97609788-0, 8-97367552-5,8-97602803-1,8-97601156-1,8-97602485-6,8-97306073-2,8-97306071-2,8-98284393-0, 8-98167556-2,8-98140249-3,8-98139816-3,8-98030550-4,1-15300436-1,8-97610254-4,8-97603099-1, 8-97603415-7,VG1246080106,VG1246080051,R61540080017A,294701-0145,2947010145, 8982191810,8981518563,8981600613,8981518373,8973297032,8981211632,8976097915,8976097896, 8976097880,8973675525,8976028031,8976011561,8976024856,8973060732,8973060712,8982843930,

8981675562,8981402493,8981398163,8980305504,1153004361,8976102544,8976030991,8976034157, 898219181-0,898151856-3,898160061-3,898151837-3,897329703-2,898121163-2,897609791-5, 897609789-6,897609788-0,897367552-5,897602803-1,897601156-1,897602485-6,897306073-2, 897306071-2,898284393-0,898167556-2,898140249-3,898139816-3,898030550-4,115300436-1, 897610254-4,897603099-1,897603415-7,8-982191810,8-981518563,8-981600613,8-981518373, 8-973297032,8-981211632,8-976097915,8-976097896,8-976097880,8-973675525,8-976028031, 8-976011561,8-976024856,8-973060732,8-973060712,8-982843930,8-981675562,8-981402493, 8-981398163,8-980305504,1-153004361,8-976102544,8-976030991,8-976034157,0950009800, 0950008970,0950008933,0950008903,0950005471,0950008170,0950006390,0950006376,0950006363, 0950005500,0950005362,0950005353,0950005344,0950005010,095000660,0950008980,0950008793, 0950008633,0950006650,0950006300,0950006270,0950005980,0950005516,0950008910,0950008011, 0950006701

1.3. 294701-0145 Injector Solenoid Valve Parameters Adaptation System: Common Rail System Injector Solenoid Valve Series: G2 series Injector Solenoid Valve Type: Solenoid Type Inductance: 145uH

314.5⁹³

1.4. 294701-0145 Injector Solenoid Valve Specifications And Dimensions Injector Solenoid Valve Size: 6cm* 3cm *3cm =54cm³ Individual Injector Solenoid Valve Weight: 130g Injector Solenoid Valve With Packaging Weight: 150g Injector Solenoid Valve Quality: China Made New Injector Solenoid Valve Packaging Size: 7cm* 5cm *5cm =175cm³ Injector Solenoid Valve Type: High Pressure Common Rail Injector Solenoid Valve Injector Solenoid Valve Minimum Order Quantity: 1 piece

1.5. 294701-0145 Injector Solenoid Valve Quality Control (1) Injector Solenoid Valve Testing

All parts of the injector solenoid valve have undergone electrical characteristics testing, precision testing, high temperature testing, low temperature testing, withstand pressure testing, leakage testing,

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.

durability testing, and various working conditions testing.

(2) Injector Solenoid Valve Installation

In addition, the injector solenoid valve production and installation process is quality controlled. Our company strictly follows the standard product installation data and product installation steps for installation, such as injector solenoid valve stroke test, injector solenoid valve solenoid valve tightening torque, injector solenoid valve nozzle tightening torque.

(3) Injector Solenoid Valve Inspection

The factory inspection of the injector solenoid valve has undergone three inspections: full inspection, random inspection, and batch inspection. Different brands of test benches are used to test the same injector solenoid valve for more than three times for factory inspection, and the fuel injector installation testing environment are progressed in dust-free workshop.

1.6. 294701-0145 Injector Solenoid Valve Customization Service

(1) Injector Solenoid Valve Customization Service Coverage: Meet OEM manufacturers' customization needs for shell engraving, logo engraving, injector solenoid valve internal packaging, injector solenoid valve external packaging and labels, etc.



(2) Injector Solenoid Valve Customization Service Requirements:

The purchase of customized injector solenoid valve is no less than 10 pieces.

The purchase of customized injector solenoid valve boxes is no less than 1000 pieces.

Customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file.

• Once the customized injector solenoid valve is sold, it can't be returned or exchanged if there is no quality problems.

| NO. | oid Valve Parts List | 2 |
|--------------|---|---|
| ANDAL SHOWLY | SPREAM SHARE SH | uneri ani ani |
| Picture | silent the set | |
| Name | Injector Solenoid Valve Assembly | Green Anti-Rust Bag |
| Description | Injector solenoid valve part number: 294701-0145 | Prevent injector solenoid valve from rusting |

/ 16

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.

st^{ypt}

57^{1,107}

No. 3 4 Picture Image: Constraint of the second secon

A Minors are prohibited from using the injector solenoid valve assembly, O-ring, nozzle protective

accessories

being damaged by external forces

cover, injector solenoid valve shell protective cover, oil return protective cover, VCI anti-rust bag, and bubble bag to avoid personal injury.

O-rings and nozzle washer shim are one-time installation accessories and need to be replaced
when installed again.

The nozzle protective cover, injector solenoid valve shell protective cover, and oil return protective cover are recyclable accessories and can be reused.

VCI anti-rust bags and bubble bags are non-degradable materials, please dispose of them properly
 after using.

The injector solenoid valve and the installation part duct must be treated with appropriate sealing oil during installation.

(2) Injector Solenoid Valve Packaging Box Size

Mob/Whatsapp: +86 13410541523Tel: +8675523215133Email :ruby@shumatt.comWebsite : www.shumatt.com© 2022 Shenzhen Shumatt Technology Co., Ltd.5 / 16



1.8. 294701-0145 Injector Solenoid Valve Testing Standards and Certificates

SPACEST

- 188⁵⁵

518.00577 We can provide the factory quality inspection test report of each injector solenoid valve to ensure that each injector solenoid valve delivered meets the engine performance indicators.

 $\mathcal{G}^{\mathbb{Z}}$

. and the

ANDER . NSTER. 1,5000 SPECTRON . SPELSTER 1,10207 SHOREY SPLIDET SPLERT 919⁵⁵ SPRINT NORT gi^{gen} SPASSA SPEEDE SPREED SPREED SRIDAT SPLIDAT STR. STR. 5172-5057 N. TORY NUT T N. T. S. T. SPREMARY SPRIMAR AND THE NURSE C SPARAT WEEK C 100^{Cl} Ø^{SE} 1,5057 95⁵¹ gi^{gen} 1205.72 SPLEIST SPALE

-st^{asta} 51^{8,000} 519.50 Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email :ruby@shumatt.com Website : www.shumatt.com © 2022 Shenzhen Shumatt Technology Co., Ltd. - 1995 - 6/16 - 16 - 16 18^{97,2}



1.9. 294701-0145 Injector Solenoid Valve Warranty Instructions (1) Product Warranty Conditions And Instructions

It is necessary to provide pictures, videos, or test reports tested by the injector solenoid valve inspection equipment when the injector solenoid valve is abnormal during use as evidence to feed back to the salesman. Abnormal conditions are properly explained such as: 1.Smoke, 2. Engine shake, 3. Difficulty starting the engine, 4. Engine noise, 5. Oil leakage etc.

(2) Injector Solenoid Valve Warranty Coverage

it;

1 After customer receives the F00RJ00841 injector solenoid valve within 15 days , if there is a performance failure and the product has no damage on surface, customer can choose to replace it or repair

(2) If the FOORJOO841 injector solenoid valve has performance problems during the warranty period (3 months), and it is confirmed to be product's problems after being tested, you can contact our salesmen to replace the same model or a reworked product with the same performance for free;

③ If the injector solenoid valve shell has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

Tips: For products not covered by warranty, our company can provide paid maintenance services. For products after paid repaired, the same performance problem will have a free warranty period within 3 months from the date of repairing.

(3) Injector Solenoid Valve Is Not Covered By Warranty

- ① The warranty period has expired.
- ② Injector solenoid valve failure caused by high temperature, high pressure, humidity, rain and snow, saline-alkali land, earthquake, and used in abnormal environment.
 - ③ Customer disassembles or repairs the injector solenoid valve personally resulting in damage to

/ 16

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.

the injector solenoid valve.

④ Injector solenoid valve damage caused by man-made reasons (throwing, strong magnetic field magnetization, set fire).

5 Injector solenoid valve failure or injector solenoid valve damage caused by non-injector solenoid valve design, technology, manufacturing, quality and other issues.

⑥ Injector solenoid valve failure due to system pressure exceeding system approved pressure.

⑦ Injector solenoid valve failure caused by system voltage exceeding approved voltage.

Injector solenoid valve failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.

Injector solenoid valve failure caused by not installing according to the tightening torque specified in the vehicle engine maintenance manual (the tightening torque is too large or too small).

(1) Injector solenoid valve failure caused by not following the installation angle specified in the vehicle engine maintenance manual.

11 Injector solenoid valve failure caused by not following the cleaning requirements specified in the vehicle engine maintenance manual.

12 Injector solenoid valve failure caused by failure to replace consumable parts as specified in the vehicle engine maintenance manual.

13 Injector solenoid valve failure caused by not complying with the intake system fit clearance and exhaust system fit clearance requirements specified in the vehicle engine maintenance manual.

14 Failure to replace the consumable parts and the fitting clearance of the oil inlet system pipeline and the injector solenoid valve connection in accordance with the fuel intake system specified in the vehicle engine maintenance manual.

1.10. 294701-0145 Injector Solenoid Valve Manufacturer Injector Solenoid Valve Manufacturer: Shenzhen Shumatt Technology Co., Ltd.

2. 294701-0145 Injector Solenoid Valve Technical Support

2.1. 294701-0145 Injector Solenoid Valve Utilized Location

(1) Example: The code of the injector solenoid valve is as follows

| | | NO. | | | | Name | | 1.000 | ١., |
|-------|--------|-----|------|-----|----|-----------------------------------|-------|--------|-----|
| ana a | Star - | A | Sec. | 50° | 32 | RQ code, quantity correction code | Stor. | S. 200 | Ş |



/ 16

2.2. 294701-0145 Injector Solenoid Valve Installation

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.

(1)F00RJ00841 Injector solenoid valve Installation Precautions:

The replacement of the injector solenoid valve must strictly follow the electrical system, the approved pressure of the low-pressure fuel intake system, the approved pressure of the high-pressure fuel circuit system, and fuel system replacement consumables requirements (including the low-pressure fuel circuit system filter and the high-pressure fuel circuit) specified in the vehicle engine maintenance manual.

A Replacement of wearing parts of the fuel system, cleaning requirements for the connection between

the fuel system and the injector solenoid valve, the fitting clearance of the injector solenoid valve connection, the installation angle and tightening torque of the injector solenoid valve, the fitting clearance of the intake system, and the fitting clearance of the exhaust system to ensure the service life of the engine and the normal operation of the injector solenoid valve.

When installing the injector solenoid valve on the engine, it is necessary to clean the engine block, cylinder head and other parts connected to the injector solenoid valve, and ensure that there is no dust, carbon deposits, water, rust spots, etc.

lacksquare Before installing, check whether the injector solenoid valve washer shim has been replaced and

installed on the injector solenoid valve.

When installing the injector solenoid valve, apply lubricant between the injector solenoid valve, fuel

10000

-13095

AND STREET

-3.77 M. C.

nozzle sealing washer shim and O-ring.

M Without replacing new washer shim can lead to: deformation of the tight cap of nozzle, deformation of

nozzle, deformation of nozzle orifice, oil leakage and air leakage, which will cause serious damage to the injector solenoid valve and nozzle to break and cause damage to the engine.

When installing the injector solenoid valve on the engine, please carefully check the components related to the installation of the injector solenoid valve, such as the injector solenoid valve pressure plate, screw, injector solenoid valve rod and other accessories are not deformed, and install it in strict accordance

with the operation steps of the engine maintenance manual.

lacksquare It is forbidden to operate the bare injector solenoid valve for a long time in an environment with lacksquare

serious dust pollution and corrosion to iron products.

lacksquare It is forbidden to operate the bare injector solenoid valve for a long time in a strong magnetic field lacksquare

environment.

 $\mu^{(\beta)}$

 $\psi^{(j)}$

 $\omega^{(2)}$

2.3. Reasons of 294701-0145 Injector Solenoid Valve Not Working Normally

(1) There is air in the oil circuit of the engine fuel system.

(2) Vehicle injector solenoid valve oil supply system is not normal.

(3) Engine common rail system oil leakage or pressure limiting valve damage.

(4) There is a short circuit, cutting out and poor contact in the wiring harness connected to the injector solenoid valve of the vehicle.

(5) The long-term placement of the injector solenoid valve causes the anti-rust oil to solidify, and the internal components are stuck or the oil holes are blocked.

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.

A Before installing, carefully check whether other components in the common rail system are damaged

so as to prevent the injector solenoid valve from not working properly after being replaced.

2.4. Causes of 294701-0145 Injector Solenoid Valve Being Damaged

- (1) Didn't operate properly according to engine maintenance manual during disassembly or installation, resulting in damage to the injector solenoid valve .
- (2) The fuel oil used for the vehicle does not meet the standard cause damage to the injector solenoid valve, such as: the water content in the fuel oil exceeds the standard, iron powder, aluminum powder, sulfide impurities exceed the standard, etc.
- (3) The engine is not regularly maintained according to the engine maintenance manual (please refer to the vehicle maintenance manual for the maintenance mileage). For example, failure to replace the lubricating oil of the engine system for a long time will cause abnormal wear of the engine, excessive exhaust gas volume or a large amount of carbon deposits inside the engine. The filter is not replaced during maintenance or the replaced filter cannot reach the original filter standard. all above reasons can cause damage to the injector solenoid valve.
- (4) The abrasion of the oil pump produces iron powder and aluminum powder enter the injector solenoid valve and cause damage to the injector solenoid valve.
- (5) The deformation and abrasion of fuel tank result in iron powder or aluminum powder entering the injector solenoid valve and causing damage to it.
- (6) The injector solenoid value is damaged due to replacement or adjustment of the relevant parts of the injector solenoid value. For example, the value clearance does not meet the standard after the engine is repaired, the replacement or modification of the wiring harness connected to the injector solenoid value fails to meet the original standard.
- (7) The engine is overheated and overloaded for a long time working results in damage to the injector solenoid valve.
- (8) The injector solenoid valve will be damaged naturally at the end of its working life.
- (9) The injector solenoid valve is magnetized (injector solenoid valve parts' magnetic exceeded) causing the injector solenoid valve to not work properly.

A Before replacing the injector solenoid valve, please check the engine parts carefully according to the engine maintenance manual to avoid the injector solenoid valve being damaged again after replacement.

2.5. 294701-0145 Injector Solenoid Valve Technical Support Obtaining Methods

- (1) Injector solenoid valve technical data: visit <u>http://shumatt.com</u> to get the technical data.
- (2) Injector solenoid valve technical videos:

Facebook: Visit <u>https://www.facebook.com/hison.li</u> to get the technical videos, constantly follow can get more information.

YouTube: <u>https://www.youtube.com/channel/UCByvYBx7VjV_mAfxh_Hu-aw</u> to get the technical videos, constantly follow can get more information.

Shumatt: Visit <u>http://shumatt.com t</u>o obtain the technical videos.

(3) Injector solenoid valve Information query software

TruckBook Parts EPC APP, download and install on Android/Apple App Store , visit <u>http://shumatt.com</u> to get the download and installation tutorial

(4) Search the Injector solenoid valve test data through TruckBook Parts EPC APP.

3. 294701-0145 Injector Solenoid Valve Purchase And Delivery

3.1. 294701-0145 Injector Solenoid Valve Purchase And Payment Term

Payment Method: T/T, Paypal, Alipay, WeChat

A Please contact our salesmen for specific payment information.

3.2. 294701-0145 Injector Solenoid Valves Main Sales Markets Main Sales Markets Of Injector Solenoid Valves: Asia, Europe, North America, South America, Africa etc.

3.3. 294701-0145 Injector Solenoid Valve Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

3.4. 294701-0145 Injector Solenoid Valve Shipping Ways

Destination in China areas: SF Express, Debon Express, the corresponding logistics company can be provided according to customer requirements in special cases.

Destinations out of China's areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers.

3.5. 294701-0145 Injector Solenoid Valve Delivery Time

Delivery Time: Send out within 3 – 7 working days after receiving payment (Except for special products and special cases).

3.6. 294701-0145 Injector Solenoid Valve Logistics Time for Destination Out of China's Areas

| DHL Logistics Time: | and the second second | all all soll | with with | S. All | an a | an a |
|-----------------------|-----------------------|--|---|--------|--|--|
| Place Of Departure | Hong Kong | Other Countries Or Regions In Asia | Australia and New Zealand | Europe | America | Other Countries |
| Mainland of China | 3 ⁷⁷ 3 | 2°° - 2°° - | 2 ^{1,000} 8-2 ^{1,000} | 8 | 8-12 | 7-10 |

UPS Logistics Timeliness:

SPLINST

Country or region of origin: Mainland Chin

| Country or reg | ion of origin: I | viainiand China | - A | | |
|----------------|------------------|-----------------|-----------|-------------|-----------|
| Country of | Estimated | Country of | Estimated | Country of | Estimated |
| Destination | Arrival | Destination | Arrival | Destination | Arrival |
| Destination | Time | Destination | Time | Destination | Time |
| Japan | 3 Days | Britain | 5-7 Days | Egypt | 5-7 Days |
| Turkey | 5-7 Days | Singapore | 3 Days | Switzerland | 5-7 Days |
| Bahrain | 5-7 Days | Latvia | 7-10 Days | New Zealand | 7-10 Days |
| Sri Lanka | 5-7 Days | Thailand | 3 Days | Austria | 5-7 Days |

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.

Tel: +8675523215133 Website : <u>www.shumatt.com</u>

11/16

| | | enzhen Shumat | | bgy CO., Llu. | A |
|-------------|-----------|---------------|-----------|----------------------|-----------|
| Romania | 5-7 Days | Vietnam | 3-5 Days | Estonia | 5-7 Days |
| Malaysia | 3-5 Days | Israel | 5-7 Days | Mexico | 7-10 Days |
| France | 5-7 Days | USA | 5-7 Days | United Arab Emirates | 5-7 Days |
| Italy | 5-7 Days | Netherlands | 5-7 Days | Bengal | 7-10 Days |
| lebanon | 5-7 Days | Philippines | 3-5 Days | Greece | 7-10 Days |
| South Korea | 3 Days | Spain | 5-7 Days | Myanmar | 5-7 Days |
| Canada | 5-7 Days | Germany | 5-7 Days | Saudi Arabia | 7-10 Days |
| Portugal | 5-7 Days | Australia | 5-7 Days | South Africa | 7-10 Days |
| Denmark | 5-7 Days | Belgium | 5-7 Days | Ukraine | 7-10 Days |
| india 🕬 | 7-10 Days | Qatar | 7-10 Days | Poland | 5-7 Days |
| Indonesia | 3-5 Days | Morocco | 7-10 Days | Pakistan | 7-10 Days |
| Kuwait | 7-10 Days | in the second | der. | . 57° - 10°° - 5 | Red Land |
| Str. Str. | 200 | Stor Stor | 41° - 41 | a da da | Stor. |

lacksquare The logistics time is for reference only, subjects are according to the actual arrival.

3.7. 294701-0145 Injector Solenoid Valve Shipping Package

States

SPANES

SHAMON

NUMPE

Domestic express packaging: Usually wrapped in waterproof scotch tape, such as picture No.1. **International express packaging:** Wrapped with waterproof yellow tape after wrapping the black protective film, such as picture No. 2.

Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 3, also, the products can be packaged according to customers' requirements.

A The packing tray is made of plastic and can be recycled.

A Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are

non-degradable materials, please dispose of them properly.

A Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film,

12/16

and white wrapping protective film to avoid personal injury.



Pic No. 1 Domestic express packaging: Wrapped with Transparent tape





Pic No.2

International express packaging: Wrapped with yellow tape after wrapping

black protective film

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.

Pic No. 3

SPANOST

Pallet Shipping: Use pallet that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties

4. 294701-0145 Injector Solenoid Valve Storage Standards

(1) Choose a suitable storage place

The warehouse and cargo yard where the injector solenoid valves are stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acid, alkali, salt and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry.

(2) Strict storage requirements

Strict inspections should be carried out when the injector solenoid valves are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do anti-rust treatment in time. Packaged injector solenoid valves must be protected from damage.

(3) Keep the warehouse dry and do moisture-proof work

The relative humidity is usually below 70% for the injector solenoid valves placed in the room, and the corrosion of the injector solenoid valves is significantly reduced.

Injector solenoid valves must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content.

(4) Reasonable stacking

After the injector solenoid value is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the injector solenoid value from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse.

If the injector solenoid valve package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.


It is forbidden to leave the injector solenoid valve exposed in the air for a long time.

f A It is forbidden to store acid, alkali, salt and other substances together with the injector solenoid

13 / 16

91⁹³⁰

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.



Email: ruby@shumatt.com

Website: www.shumatt.com

Shenzhen Office: 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway Station, Bao'an District, Shenzhen, China Mainland

Shenzhen Office: Exit C, Qiao Touxi Metro Station, No. 66 Chongqing Road, Fuhai Avenue, Bao'an District, Shenzhen, China Mainland

Hong Kong Office: Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

After-Sales Service Address: Please contact our salesmen to obtain and provide the corresponding

product maintenance reasons (Reference: <u>1.9. F00RJ00841 Injector solenoid valve Warranty Instructions</u>)

| NO. | Name | WeChat/Whatsapp | E-mail |
|------|---|---|---|
| 1 | Ruby | +86-13410541523 | ruby@shumatt.com |
| 2 | lvy s | +86-18025309821 | sales@shumatt.com |
| 3 | Rebecca | +86-18025349821 | sales01@shumatt.com |
| 4 | Janny | +86-18028749821 | sales02@shumatt.com |
| 5.00 | Sam | +86-13316859821 | Sales8@shumatt.com |
| 6 | Natalie | +86-18938945856 | sales15@shumatt.com |
| 7 | Ada | +86-1342286353 | sales5@shumatt.com |
| 8 | Hison Li | +86-18318811871 | web@shumatt.com |
| 9 | Mecca | +86-18938948618 | sales11@shumatt.com |
| 10 | Eric | +86 18319033618 | sales3@shumatt.com |
| 11 | Wayne (Joaquín enespañol) | +86-13316959821 | wayne@shumatt.com |
| 12 | Sylvia | +86 18312499884 | sales6@shumatt.com |
| 24.6 | Visit <u>http://s</u> | humatt.comfor the latest sales staff | information |
| | 1 2 3 4 5 6 7 8 9 10 11 | 1Ruby2Ivy3Rebecca4Janny5Sam6Natalie7Ada8Hison Li9Mecca10Eric11Wayne (Joaquín enespañol)12Sylvia | 1 Ruby +86-13410541523 2 Ivy +86-18025309821 3 Rebecca +86-18025349821 4 Janny +86-18028749821 5 Sam +86-13316859821 6 Natalie +86-18938945856 7 Ada +86-1342286353 8 Hison Li +86-18318811871 9 Mecca +86-18938948618 10 Eric +86 18319033618 11 Wayne (Joaquín enespañol) +86-13316959821 |

5.2. Sales Contact Information

Note: The emails of Shumatt sales staff all end with @shumatt.com

6. Copyright Statement

्रती

The copyright of any contents in this file "Injector Solenoid Valve 294701-0145 Technical File" (including but not limited to parameters, data, text, charts, images, sounds, videos, etc.) belongs to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify, duplicate, republish any content in "Injector Solenoid Valve 294701-0145 Technical File" in any way. At the same time, any conditions to spread, re-post, display the contents of "Injector Solenoid Valve 294701-0145 Technical File" should indicate the source of the quoted article, Shenzhen Shumatt Technology Co., Ltd. Any actions failure to follow above conditions violate the "Copyright Law of the People's Republic of China" and other laws and regulations as well as relevant provisions of international conventions.

15 / 16

Mob/Whatsapp: +86 13410541523 Email :<u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd.